



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 7913L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER	CUT	165.00	165.00
1	FRONT FORK ASSY	NOT NECESSARY	1,080.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	400.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	225.00	-
1	FRONT RIM BEARING	NOT NECESSARY	80.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	98.00	-
1	FRONT SIDE COVER LH	CUT	285.00	285.00
1	HEADLAMP	NOT NECESSARY	960.00	-
1	SIDE MIRROR N/S	CUT	180.00	180.00
1	HANDLE BAR	BENT	225.00	225.00
1	SET HANDLE BAR BALANCER	N/S CUT	125.00	40.00
1	SET HAND GRIP	NOT NECESSARY	70.00	-
1	BRAKE LEVER - L/H	CUT	120.00	80.00
1	FOOTSTEP PANEL - L/H	CUT	230.00	230.00
1	FOOTSTEP LOWER COVER	CUT	265.00	265.00
1	REAR COVER	CUT	320.00	260.00
1	AIR FILTER COVER	SERVICEABLE	175.00	-
1	REAR FOOTREST - L/H	CUT	155.00	120.00
1	SIDE STAND	CUT	115.00	115.00
1	MAIN STAND	TO REPAIR SEE LABOUR	155.00	-
	LESS 10% DISCOUNT		-542.80	-196.50
			4,885.20	1,768.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEAL (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX (SN)	CUT	480.00	280.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-

Report Ref No. CS/INC23001297/Uwy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PCX EMBLEM (SN)  <u>LABOUR</u>  TO CHECK WIRING AND RESET HEADLAMP FOCUSING. TO RESPRAY PAINTING.  TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT RIM AND MAIN STAND.	NECESSARY	80.00	40.00
			984.00	320.00
		NOT NECESSARY	80.00	-
			650.00	200.00
			480.00	300.00
			1,210.00	500.00
GRAND TOTAL			7,079.20	2,588.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,000.00

Report Ref No. CS/INC23001297/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.