

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23001303/UNY3M4**Date:** 06/04/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001959209		
<b>Claimant Vehicle No :</b>	SLS3511E	<b>Insured Vehicle No :</b>	SLX9560Y		
Date of Loss:	28/01/2023	Nature of Claim:	TP	Claim No:	301128

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLS3511E</b>		
Make & Model:	MERCEDES-BENZ E200, 2.0 M-HYBRID EXCLUSIVE SALOON (A)	Engine No:	26492030347642
Reg. Date:	19/04/2021 (Man. Year: 2020)	Chassis No:	W1K2130802A905875
Colour:	Blue	Odometer:	44878 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/35 ZR20	Rear Tyre Size:	235/35 ZR20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,123.00	4,044.01	9,078.99	69.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,270.00	2,280.00	64.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,673.00</b>	<b>5,314.01</b>	<b>11,358.99</b>	<b>68.13</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	16,673.00	4,200.00	12,473.00	74.81
<b>+ GST 8.00/8.00% (S\$)</b>	1,333.84	336.00	997.84	74.81
<b>Nett Amount (S\$)</b>	<b>18,006.84</b>	<b>4,536.00</b>	<b>13,470.84</b>	<b>74.81</b>

**INSPECTION**

Date of Assignment:	07/02/2023		
Date Inspected:	21/03/2023	Inspected At:	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-87 AUTOBAY@KAKI BUKIT SINGAPORE 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2023)
Parts:	143	MERCEDES-BENZ E200 2.0 M-HYBRID EXCLUSIVE SALOON (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS3511E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*KICK SENSOR 2PIECES	Cracked (1Piece Only)	380.00 FL	*190.00 FL
2	1		*REAR BOOT E200 EMBLEM	Necessary	165.00 FL	*102.00 FL
3	1		*REAR BOOT LOGO EMBLEM	Not Necessary	75.00 FL	*- FL
4	1		*REAR BOOT LID	Repair	2,950.00 FL	*- FL
5	1		*REAR BOOT LID CHROME	Not Necessary	130.00 FL	*- FL
6	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	265.00 FL	*- FL
7	2		*REAR BOOT TAILLIGHT L/R	Not Necessary	1,204.00 FL	*- FL
8	1		*REAR BUMPER	Dented/Deformed	2,320.00 FL	*2,171.46 FL
9	1		*REAR BUMPER CENTRE BRACKET	Cracked	125.00 FL	*125.00 FL
10	1		*REAR BUMPER CHROME CENTRE	Cracked	430.00 FL	*389.53 FL
11	2		*REAR BUMPER CHROME SIDE L/R	Serviceable	130.00 FL	*- FL
12	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	124.00 FL	*- FL
13	2		*REAR BUMPER RETAINER L/R	Not Necessary	408.00 FL	*- FL
14	1		*REAR END PANEL	Repair	2,115.00 FL	*- FL
15	1		*REAR REINFORCEMENT BEAM	Bent	1,115.00 FL	*1,039.80 FL
16	2		*REAR TAIL LAMP L/R	Not Necessary	1,694.00 FL	*- FL
17	1		*REVERSE SENSOR 4PIECES	Shorted (2Pieces Only)	840.00 FL	*420.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
19	1		*SET REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,570.00	4,487.79
- List Item Discount on L Items 10.00/10.00% (S\$)					1,447.00	443.78
Total Parts (S\$)					13,123.00	4,044.01

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	120.00	20.00
2	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	0.00
3	TO REMOVE, REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	150.00	50.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,300.00	600.00
6	TO RECALIBRATE REVERSE SENSOR ASSY	New	450.00	0.00
7	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL	New	180.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,550.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >