

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI23001307/AQY3Q2**Date:** 29/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SLU4055M **Insured Vehicle No :** SLC7697K

Date of Loss: 05/02/2023 Nature of Claim: TP Claim No: CDMPG23000302-002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU4055M**

Make & Model: MAZDA 3, 1.5 (A) Engine No: PE21019914

Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: JM6BN2478J0193616

Colour: White Odometer: 59081 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,439.03	6,324.47	8,114.56	56.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	2,130.00	1,960.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,529.03</b>	<b>8,454.47</b>	<b>10,074.56</b>	<b>54.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,529.03</b>	<b>6,700.00</b>	<b>11,829.03</b>	<b>63.84</b>

INSPECTION

Date of Assignment: 07/02/2023

Date Inspected: 07/02/2023 Inspected At: JDM AUTOCARE (HQ)  
1 KAKI BUKIT AVENUE 6 #01-51, Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Mar 2023)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4055M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT LOWER ARM	Bent	541.30 FL	*541.30 FL
2	1		*LH FRONT KNUCKLE ARM	Damaged	681.40 FL	*681.40 FL
3	1		*LH FRONT KNUCKLE ARM BEARING	Damaged	198.40 FL	*198.40 FL
4	1		*LH FRONT SHOCK ABSORBER	Not Necessary	542.80 FL	*- FL
5	1		*FRONT STEERING RACK & PINION	Not Necessary	1,493.70 FL	*- FL
6	1		*LH FRONT DRIVE SHAFT	Not Necessary	112.60 FL	*- FL
7	1		*LH FRONT BUMPER SIDE RETAINER	Not Necessary	65.70 FL	*- FL
8	1		*LH FRONT FENDER	Dented	348.71 FL	*348.71 FL
9	1		*LH FRONT FENDER INNER COWLING	Deformed	134.80 FL	*134.80 FL
10	1		*LH FRONT DOOR	Dented	1,228.97 FL	*1,228.97 FL
11	2		*LH FRONT DOOR HINGE	Bent	165.90 FL	*165.90 FL
12	1		*LH FRONT DOOR CHECKER	Not Necessary	126.10 FL	*- FL
13	1		*LH FRONT DOOR INNER TRIM	Cracked	658.10 FL	*658.10 FL
14	1		*LH FRONT DOOR WEATHERSTRIPE	Cut	260.40 FL	*260.40 FL
15	1		*LH FRONT DOOR STICKER	Necessary	156.10 FL	*156.10 FL
16	1		*LH FRONT DOOR OUTER MOULDING	Not Necessary	212.30 FL	*- FL
17	1		*LH FRONT DOOR OUTER HANDLER	Not Necessary	259.70 FL	*- FL
18	1		*LH FRONT DOOR POWER WINDOW MOTOR	Not Necessary	564.20 FL	*- FL
19	1		*LH FRONT DOOR GLASS	Not Necessary	567.30 FL	*- FL
20	1		*LH FRONT DOOR GLASS CHANNEL RUBBER	Not Necessary	126.80 FL	*- FL
21	1		*LH FRONT DOOR MIRROR	Damaged	698.30 FL	*698.30 FL
22	1		*LH FRONT DOOR MIRROR COVER	Repair	112.80 FL	*- FL
23	1		*LH ROCKER PANEL OUTER PANEL	Repair	1,154.20 FL	*- FL
24	1		*LH REAR DOOR	Dented	1,175.41 FL	*1,175.41 FL
25	2		*LH REAR DOOR HINGE	Not Necessary	165.90 FL	*- FL
26	1		*LH REAR DOOR CHECKER	Not Necessary	126.10 FL	*- FL
27	1		*LH REAR DOOR INNER TRIM	Not Necessary	658.10 FL	*- FL
28	1		*LH REAR DOOR WEATHERSTRIPE	Not Necessary	260.40 FL	*- FL
29	1		*LH REAR DOOR STICKER	Necessary	156.10 FL	*156.10 FL
30	1		*LH REAR DOOR OUTER MOULDING	Not Necessary	212.30 FL	*- FL
31	1		*LH REAR DOOR OUTER HANDLER	Not Necessary	259.70 FL	*- FL
32	1		*LH REAR DOOR POWER WINDOW MOTOR	Not Necessary	564.20 FL	*- FL
33	1		*LH REAR DOOR POWER WINDOW REGULATOR GEAR	Not Necessary	664.20 FL	*- FL
34	1		*LH FRONT DOOR POWER WINDOW REGULATOR GEAR	Damaged	664.20 FL	*664.20 FL
35	1		*LH REAR DOOR GLASS	Not Necessary	567.30 FL	*- FL
36	1		*LH REAR DOOR GLASS CHANNEL RUBBER	Not Necessary	126.80 FL	*- FL
37	1		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
38	1		*LH FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*30.00 FS
39	1		*LH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
40	1		*LH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
41	1		*LH FRONT SPORT RIM	Cut	950.00 FS	*580.00 FS
42	1		*LH FRONT TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)17,641.297,738.09

- List Item Discount on L Items 20.00/20.00% (\$\$)3,202.261,413.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>14,439.03</b>
						<b>6,324.47</b>
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REINSTALL ALL ELECTRICAL WIRING ,LIGHTING	New	80.00	30.00
2	TO SUPPLY LABOUR ,WORKMANSHIP TO REMOVE AND REINSTALL AFFECTED AREAS	New	1,500.00	800.00
3	TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS	New	1,200.00	800.00
4	TO APPLY TUFF COAT	New	300.00	60.00
5	TO TRANSFER LH BOTH DOOR GLASS	New	260.00	80.00
6	TO TRANSFER LH BOTH DOOR FITTING	New	300.00	80.00
7	TO REMOVE & RENEW LH FRONT UNDERCARRIAGE	New	300.00	200.00
8	WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,090.00</b>	<b>2,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >