

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001310/TPA3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002995265
Claimant Vehicle No :	SMP6843G	Insured Vehicle No :	YP1743C
Date of Loss:	05/02/2013	Nature of Claim:	TP
		Claim No:	202332005232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6843G		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHX6113
Reg. Date:	10/10/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH002526
Colour:	Silver	Odometer:	30893 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,719.00	15,311.00	2,408.00	13.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,230.00	20,250.00	5,980.00	22.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	43,949.00	35,561.00	8,388.00	19.09
+ GST 8.00/8.00% (S\$)	3,515.92	2,844.88	671.04	19.09
Nett Amount (S\$)	47,464.92	38,405.88	9,059.04	19.09
+ Car Rental (27.0 x S\$108.00/day) (S\$)		2,916.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		41,323.88		

INSPECTION

Date of Assignment:	07/02/2023	
Date Inspected:	09/02/2023 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	27.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jun 2023)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6843G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	60.00 FS	*- FS
2	1		*C&C EMBLEM	Necessary	50.00 FS	*50.00 FS
3	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
4	1		*HEADLAMP ASSY ,LH	Cracked	1,233.00 FS	*1,233.00 FS
5	1		*LAMP ASSY ,COMB ,RR LH	Cracked	661.00 FS	*661.00 FS
6	1		*LAMP ASSY ,COMB ,RR RH	Cracked	661.00 FS	*661.00 FS
7	1		*REFLECTOR	Not Necessary	28.00 FS	*- FS
8	1		*REFLECTOR	Not Necessary	28.00 FS	*- FS
9	2		*LAMP ASSY ,LICENSE PLATE	Not Necessary	106.00 FS	*- FS
10	1		*LAMP ASSY ,FOG ,FR LH	Not Necessary	315.00 FS	*- FS
11	1		*FACE ,FR BUMPER	Deformed	995.00 FS	*995.00 FS
12	1		*GARNISH ,FR BUMPER ,LH	Deformed	157.00 FS	*157.00 FS
13	1		*GRILLE ,FR UNDER	Not Necessary	203.00 FS	*- FS
14	1		*BRACKET ,FR BUMPER ,LH	Distorted	16.00 FS	*16.00 FS
15	1		*FACE ,RR BUMPER	Deformed	1,268.00 FS	*1,268.00 FS
16	1		*BRACKET ,RR BUMPER ,LH	Deformed	34.00 FS	*34.00 FS
17	1		*BRACKET ,RR BUMPER ,RH	Deformed	34.00 FS	*34.00 FS
18	1		*FENDER ,FR LH	Bent	652.00 FS	*652.00 FS
19	1		*FLOOR ,RR	Not Necessary	986.00 FS	*- FS
20	1		*PANEL ,RR END	Bent	440.00 FS	*440.00 FS
21	3		*SPACER ,RR WINDOW	Necessary	33.00 FS	*33.00 FS
22	2		*STOPPER ,WINDSHIELD GLASS	Necessary	8.00 FS	*8.00 FS
23	1		*GLASS ,RR WINDOW	Not Necessary	561.00 FS	*- FS
24	1		*HINGE ,TRUNK LID ,LH	Bent	209.00 FS	*209.00 FS
25	1		*HINGE ,TRUNK LID ,RH	Bent	209.00 FS	*209.00 FS
26	1		*WEATHERSTRIP ,TRUNK LID	Twisted	161.00 FS	*161.00 FS
27	1		*PANEL ,TRUNK LID	Bent	820.00 FS	*820.00 FS
28	1		*LATCH ,TRUNK LID	Bent	224.00 FS	*224.00 FS
29	1		*GARNISH ,RR END PANEL	Deformed	346.00 FS	*346.00 FS
30	1		*MARK ,THREE-DIA	Necessary	86.00 FS	*86.00 FS
31	1		*MARK ,ATTRAGE	Necessary	26.00 FS	*26.00 FS
32	1		*TRIM ,RR END	Deformed	68.00 FS	*68.00 FS
33	1		*PANEL ,QTR ,OTR LH	Buckled	1,336.00 FS	*1,336.00 FS
34	1		*PANEL ,QTR ,OTR RH	Buckled	1,324.00 FS	*1,324.00 FS
35	1		*PANEL ,RR COMB LAMP HSG LH	Bent	62.00 FS	*62.00 FS
36	1		*PANEL ,RR COMB LAMP HSG RH	Bent	62.00 FS	*62.00 FS
37	1		*EXTN ,QTR PANEL ,UPR OTR LH	Bent	122.00 FS	*122.00 FS
38	1		*EXTN ,QTR PANEL ,UPR OTR RH	Bent	122.00 FS	*122.00 FS
39	1		*SHIELD ,FR WHEELHOUSE ,LH	Not Necessary	101.00 FS	*- FS
40	1		*PANEL ASSY ,FR END	Bent	1,307.00 FS	*1,307.00 FS
41	4		*GROMMET ,RR END TRIM	Necessary	16.00 FS	*16.00 FS
42	4		*CLIPS	Necessary	12.00 FS	*12.00 FS
43	1		*BUZZER ,KEYLESS OPERATIO RR	Cracked	94.00 FS	*94.00 FS
44	1		*COVER ,RR VENTILATOR	Deformed	50.00 FS	*50.00 FS
45	1		*BOARD ,TRUNK ROOM FLOOR	Deformed	201.00 FS	*201.00 FS
46	1		*TRIM ,TRUNK ROOM SIDE ,LH	Deformed	165.00 FS	*165.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*CAP ,TAIL LAMP	Deformed	6.00 FS	*6.00 FS
48	10		*CLIPS	Necessary	40.00 FS	*40.00 FS
49	10		*CLIPS	Necessary	30.00 FS	*30.00 FS
50	1		*COVER ,RELAY BOX	Deformed	66.00 FS	*66.00 FS
51	1		*BOX ASSY ,RELAY	Deformed	144.00 FS	*144.00 FS
52	1		*MUD GUARD ,RR RH	Deformed	50.00 FS	*50.00 FS
53	1		*SKRIKER ,TRUNK LID LATCH	Bent	21.00 FS	*21.00 FS
54	1		*UNPAINTED BODYKITS	Deformed	1,643.00 FS	*1,643.00 FS
55	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
					F=Franchise part. S=SpcNett.	
					Total Parts (S\$)	17,719.00 15,311.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ACCIDENT TOWING FEE	New	120.00	120.00
2	REPLACE FRONT SUPPORT PANEL	New	640.00	640.00
3	REMOVE & REINSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR	New	160.00	160.00
4	RESPRAY FRONT SUPPORT PANEL	New	550.00	550.00
5	PULL ON FLOOR PANEL	New	500.00	500.00
6	REPLACE QUARTER PANEL EXTENSION LH & RH REPAIR REAR FLOOR PANEL	New	960.00	960.00
7	RESPRAY REAR FLOOR PANEL	New	550.00	550.00
8	REPLACE FUSE BOX & RELAY BOX	New	320.00	320.00
9	VACUUM & TOP UP A/COND GAS	New	80.00	80.00
10	REPLACE FRT BUMPER ,FRT LH FENDER ,BODY KIT & AFFECTED AREA	New	2,560.00	1,600.00
11	PAINT WORK ON FRT BUMPER ,FRT LH FENDER ,FRT LH DOOR PANEL & BODY KIT	New	2,750.00	2,200.00
12	REPLACE REAR BUMPER ,BOOT ,BOTH REAR FENDER ,END PANEL ,FLOOR PANEL,BODY KIT & BOTH REAR ,TAIL LAMP PANEL REPAIR ON REAR BOTH BOOT SIDE EXTENTION	New	8,960.00	6,400.00
13	PAINT WORK ON REAR BUMPER ,BOOT ,BODY KIT ,END PANEL,FLOOR PANEL,BOTH REAR TAIL LAMP PANEL & BOTH REAR FENDER	New	5,500.00	3,850.00
14	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	150.00	100.00
15	REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR	New	300.00	300.00
16	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
17	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	180.00	160.00
18	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL	New	200.00	180.00
19	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	180.00	160.00
20	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	640.00	640.00
21	TO APPLY SEALANT ON AFFECTED AREA	New	240.00	200.00
22	PERFORM RUST PREVENTION	New	180.00	100.00
23	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	150.00	120.00
24	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (S\$)			26,230.00	20,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >