

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23001312/PA3Q2**Date:** 25/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle No : SLT1890T **Insured Vehicle No :** SLQ9272R

Date of Loss: 05/02/2023 Nature of Claim: TP Claim No: MFL2023D0001816

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT1890T**
 Make & Model: HONDA CITY, 1.5 L I-VTEC (A) Engine No: L15A71809414
 Reg. Date: 14/03/2011 (Man. Year: 2009) Chassis No: MRHGM26509P020380
 Colour: Metallic Red Odometer: 247950 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: West Lake 8 mm Rear Left Side: West Lake 8 mm
 Front Right Side: West Lake 8 mm Rear Right Side: West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,403.80	2,412.46	5,991.34	71.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,630.00	1,370.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,403.80	4,042.46	7,361.34	64.55
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	11,403.80	3,100.00	8,303.80	72.82
+ GST 8.00/8.00% (S\$)	912.30	248.00	664.30	72.82
Nett Amount (S\$)	12,316.10	3,348.00	8,968.10	72.82
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		3,974.75		

INSPECTION

Date of Assignment: 07/02/2023

Date Inspected: 08/02/2023 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	143	HONDA CITY 1.5 L I-VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1890T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,213.00 FL	*503.90 FL
2	1		*BOOTLID INNER TRIM	Serviceable	181.00 FL	*- FL
3	2		*BOOTLID HINGE	Repair	134.00 FL	*- FL
4	1		*BOOTLID LOCK	Dented	259.00 FL	*68.00 FL
5	1		*BOOTLID RELEASE CABLE	Serviceable	53.00 FL	*- FL
6	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Dented	148.00 FS	*92.50 FS
7	1		*BOOTLID CITY EMBLEM	Necessary	47.00 FL	*47.00 FL
8	1		*BOOTLID I-VTEC EMBLEM	Necessary	42.00 FL	*42.00 FL
9	2		*LICENCE PLATE LAMP	Serviceable	144.00 FL	*- FL
10	1		*BOOTLID OUTER CHROME GARNISH	Serviceable	117.00 FL	*- FL
11	2		*BOOTLID HINGE GARNISH	Serviceable	98.00 FL	*- FL
12	1		*BOOTLID HONDA LOGO	Necessary	61.00 FL	*61.00 FL
13	1		*END PANEL	Bent	732.00 FL	*399.30 FL
14	1		*END PANEL TOP GARNISH	Mtg Cracked	164.00 FL	*98.00 FL
15	1		*SPARE TYRE FLOOR PANEL	Repair	895.00 FL	*- FL
16	1		*SPARE TYRE TOP BOARD	Serviceable	127.00 FL	*- FL
17	1		*REAR BUMPER	Buckled	988.00 FL	*463.70 FL
18	1		*REAR BUMPER SIDE RETAINER	O/S Distorted	114.00 FL	*57.00 FL
19	1		*REAR BUMPER REINFORCEMENT	No such part	576.00 FL	*- FL
20	1		*REAR BUMPER LOWER COWLING	Serviceable	188.00 FL	*- FL
21	2		*TAILLAMP	Cracked / Dented	1,378.00 FL	*822.80 FL
22	2		*TAILLAMP SPONGE SEAL	Necessary	16.00 FL	*16.00 FL
23	2		*TAILLAMP PANEL	Repair	294.00 FL	*- FL
24	2		*TAILLAMP LOWER BRACKET	Serviceable	66.00 FL	*- FL
25	1		*EXHAUST ASSY	Repair	883.00 FL	*- FL
26	2		*EXHAUST ASSY MOUNTING	Serviceable	82.00 FL	*- FL
27	1		*EXHAUST ASSY HEATSHIELD	Repair	119.00 FL	*- FL
28	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
29	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS
30	1		*REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
31	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS
32	10		*REAR BUMPER CLIPS	Not Necessary	45.00 FS	*- FS
33	6		*TAILLAMP CLIPS	Not Necessary	27.00 FS	*- FS
34	1		*SPARE TYRE FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
35	1		*END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
36	6		*END PANEL TOP GARNISH CLIPS	Necessary	27.00 FS	*27.00 FS
37	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,198.00	2,928.20
- List Item Discount on L Items 20.00/20.00% (\$)	1,794.20	515.74
Total Parts (\$)	8,403.80	2,412.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTION .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	600.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE ,REFIT BOOTLID COMPONENTS AND REPLACE BOOTLID ,CHECK AND RE-ADJUST CLOSE GAP ,ALIGNMENT AND WATER SEEPAGE	New	100.00	50.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	900.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	60.00
6	TO REMOVE AND REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE EXHAUST SILENCER	New	150.00	0.00
Gross Labour Cost (\$\$)			3,000.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >