

Vehicle Damage Assessment Report for [SLT1890T]

Estimate Created: 07/02/2023 15:09 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/05/2023 13:52 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	City
Engine Type			
License Plate Number	SLT1890T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$3,100.00 WITH 5 WORKING
DAYS

Insurlogic 4 (05/05/2023 13:48)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Bootlid		1	303.90	-20.00 %	243.12
Bootlid lock		1	68.00	-20.00 %	54.40
Bootlid weatherstrip		1	92.50	-20.00 %	74.00
Bootlid City emblem		1	47.00	-20.00 %	37.60
Bootlid I-VTEC emblem		1	42.00	-20.00 %	33.60
Bootlid Honda logo		1	61.00	-20.00 %	48.80
Rear end panel		1	399.30	-20.00 %	319.44
Rear end panel top garnish		1	98.00	-20.00 %	78.40
Rear bumper		1	463.70	-20.00 %	370.96
Rear bumper side retainer		1	57.00	-20.00 %	45.60
Taillamp		2	411.40	-20.00 %	658.24
Taillamp sponge seal		2	8.00	-20.00 %	12.80

Parts Subtotal 1,976.96

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Reverse sensor		1.0	200.00	0.00 %	200.00
Rear end panel sealant		1.0	30.00	0.00 %	30.00
Rear end panel top garnish clips		1.0	27.00	0.00 %	27.00

Materials Subtotal 257.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	600.00	0.00 %	600.00
Check wiring	RnR	20.00	0.00 %	20.00
To remove and refit bootlid component and replace bootlid, check and re-adjust close cap, alignment and water seepage.	RnR	50.00	0.00 %	50.00
To rush proof all affected portion after repair.	RnR	60.00	0.00 %	60.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Bootlid hinge	Medium	0.00	0.00 %	0.00
Exhaust assy	Medium	0.00	0.00 %	0.00

Exhaust assy heatshield	Medium	0.00	0.00 %	0.00
Spare tyre floor panel	Medium	0.00	0.00 %	0.00
Taillamp panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	900.00	0.00 %	900.00
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		730.00
		Paint Labor Subtotal		900.00
		Labor Subtotal		1,630.00

Summary

Repair Cost	3,863.96
Discount(20 %)	(772.79)
	3,091.17
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,091.17