

ASS. REC. BY:

REF:

GRB/23 001312/KP

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 835k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 01/26 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT 1890T Yr Regn: 03, 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda City C.C. 1497Colour: M. Red A/C: Insured / Std / NI / NASp. Reading: 247950 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NRHGM26509P020380Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 5/2/23D.O.I. 8/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EN NOT ready10/2 11pm @ 3100 Calm

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA CITY

Engine/Chassis No.: MRHGM26509P020380


Date of accident: 05.02.23

Damaged area: Rear

Date: 07/02/2023

Claim Type: TP

VRN: SLT1890T



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bootlid 503.90	1	\$ 1,213.00	\$ 1,213.00	X
2	Bootlid inner trim	1	\$ 181.00	\$ 181.00	X
3	Bootlid hinge	2	\$ 67.00	\$ 134.00	X
4	Bootlid lock 68	1	\$ 259.00	\$ 259.00	X
5	Bootlid release cable	1	\$ 53.00	\$ 53.00	X
6	Bootlid weatherstrip	1	\$ 185.00	\$ 185.00	506.92.50
7	Bootlid "CITY" emblem	1	\$ 47.00	\$ 47.00	—
8	Bootlid "i-VTEC" emblem	1	\$ 42.00	\$ 42.00	—
9	Licence plate lamp	2	\$ 72.00	\$ 144.00	X
10	Bootlid outer chrome garnish	1	\$ 117.00	\$ 117.00	X
11	Bootlid hinge garnish	2	\$ 49.00	\$ 98.00	X
12	Bootlid "HONDA" logo	1	\$ 61.00	\$ 61.00	—
13	End panel 399.30	1	\$ 732.00	\$ 732.00	—
14	End panel top garnish 98	1	\$ 164.00	\$ 164.00	—
15	Spare tyre floor panel	1	\$ 895.00	\$ 895.00	X
16	Spare tyre top board	1	\$ 127.00	\$ 127.00	X
17	Rear bumper 463.70	1	\$ 988.00	\$ 988.00	—
18	Rear bumper side retainer	2	\$ 57.00	\$ 114.00	4
19	Rear bumper reinforcement	1	\$ 576.00	\$ 576.00	X
20	Rear bumper lower cowl	1	\$ 188.00	\$ 188.00	X
21	Taillamp C 411.40	2	\$ 689.00	\$ 1,378.00	822.80
22	Taillamp sponge seal	2	\$ 8.00	\$ 16.00	—
23	Taillamp panel	2	\$ 147.00	\$ 294.00	X
24	Taillamp lower bracket	2	\$ 33.00	\$ 66.00	X
25	Exhaust assy	1	\$ 883.00	\$ 883.00	X
26	Exhaust assy mounting	2	\$ 41.00	\$ 82.00	X
27	Exhaust assy heatshield	1	\$ 119.00	\$ 119.00	X
Subtotal				\$ 9,156.00	
List discount				20.00%	
Total				\$ 7,324.80	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
2	Reverse camera	1	\$ 350.00	\$ 350.00
3	Reverse sensor	1	\$ 280.00	\$ 280.00
4	Bootlid inner trim clips	10	\$ 4.50	\$ 45.00
5	Rear bumper clips	10	\$ 4.50	\$ 45.00
6	Taillamp clips	6	\$ 4.50	\$ 27.00
7	Spare tyre floor panel sealant	1	\$ 100.00	\$ 100.00
8	End panel sealant	1	\$ 100.00	\$ 100.00
9	End panel top garnish clips	6	\$ 4.50	\$ 27.00
10	Sundries	1	\$ 50.00	\$ 50.00
			Total	\$ 1,079.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
6	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer.	0.75	\$ 150.00
		Total labour	\$ 3,000.00

Estimate Grand Total	\$ 11,403.80
-----------------------------	---------------------

