



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 5244M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET SIDE MIRROR	CUT	120.00	60.00
1	CLUTCH LEVER	BROKEN	110.00	40.00
1	FRONT MUDGUARD	CUT	140.00	85.00
1	FRONT HEADLIGHT COVER	NOT NECESSARY	140.00	-
1	FRONT SIGNAL LHS	CUT	110.00	75.00
1	FRONT SIGNAL RHS	NOT NECESSARY	110.00	-
1	FRONT LHS Z PANEL	CRACKED	180.00	100.00
1	FRONT BASKET	CRACKED	140.00	65.00
1	GEAR SELECTOR LEVER	BENT	130.00	60.00
1	RIDER FOOTREST BRACKET	BENT	140.00	140.00
1	SIDE STAND	BENT	150.00	60.00
1	MAINSTAND	BENT	180.00	95.00
1	HANDLE GRIP	CUT	80.00	50.00
1	HANDLE BAR	BENT	140.00	120.00
1	REAR LHS TAIL COVER	CUT	140.00	120.00
1	PILLION FOOTREST BRACKET LHS	NOT NECESSARY	120.00	-
1	PILLION FOOTREST LHS	CUT	100.00	50.00
1	CHAIN COVER	NOT NECESSARY	120.00	-
1	REAR TAIL TIDY	CUT	180.00	55.00
1	REAR SIGNAL LHS	CUT	110.00	60.00
1	STEERING CONE BEARING	NECESSARY	220.00	50.00
1	SET FORK	BENT	420.00	350.00
1	FRONT RIM	NOT NECESSARY	450.00	-
1	FORK UNDER BRACKET T CONE	BENT	220.00	65.00
1	FRONT TYRE	NOT NECESSARY	200.00	-
1	FRONT LHS FOOTPEG	DENTED	120.00	50.00
1	FRONT LHS FOOTPEG RUBBER	CUT	100.00	45.00
1	HANDLEBAR COVER	NOT NECESSARY	140.00	-
1	FRONT DRL UNDER COVER	NOT NECESSARY	150.00	-
1	KEYSWITCH COVER	NOT NECESSARY	140.00	-
1	TAIL TIDY BRACKET	NOT NECESSARY	160.00	-

Report Ref No. CS/SMR23001322/Twy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-496.00	-179.50
			4,464.00	1,615.50
	LABOUR			
	FORK ALIGNMENT.		220.00	120.00
	FRONT RIM ALIGNMENT.	NOT NECESSARY	220.00	-
	CHASSIS ALIGNMENT.	NOT NECESSARY	500.00	-
	LABOUR FEE.		1,200.00	300.00
			2,140.00	420.00
	GRAND TOTAL		6,604.00	2,035.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/SMR23001322/Twy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.