

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23001324/RWCE2**Date:** 01/06/2023REFERENCE

Insured/Claimant:	LAU KIAN KOON	Policy No:	7220130725	
Date of Loss:	02/02/2023	Nature of Claim:	OD	Claim No: 6419806278SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL1173J	Engine No:	DKY016361
Make & Model:	AUDI A6 DESIGN, 2.0 TFSI (140 KW) (A)	Chassis No:	WAUZZZF20NN006334
Reg. Date:	16/11/2022 (Man. Year: 2021)	Odometer:	7817 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$247,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,150.90	32,927.36	27,223.54	45.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,212.00	8,212.00	11,000.00	57.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	79,362.90	41,139.36	38,223.54	48.16
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	78,562.90	40,339.36	38,223.54	48.65
+ GST 8.00/8.00% (S\$)	6,285.03	3,227.15	3,057.88	48.65
Nett Amount (S\$)	84,847.93	43,566.51	41,281.42	48.65

INSPECTION

Date of Assignment:	08/02/2023	
Date Inspected:	06/02/2023	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,187.00 FS	*2,549.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	689.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Cracked	263.00 FS	*210.00 FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Cracked	94.00 FS	*74.40 FS
5	2		*FRONT BUMPER REINFORCEMENT - LH / RH	Not Necessary	264.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	181.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	248.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Not Necessary	298.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,026.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	78.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	62.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cracked	2,603.00 FS	*2,082.40 FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	65.00 FS	*- FS
14	1		*RADIATOR GRILLE COVER CAP	Cracked	59.00 FS	*46.48 FS
15	1		*RADIATOR GRILLE BRACKET	Not Necessary	111.00 FS	*- FS
16	4		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	1,196.00 FS	*- FS
17	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
18	1		*SET FRONT BUMPER WIRING	Not Necessary	648.00 FS	*- FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	267.00 FS	*213.20 FS
20	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,140.00 FS	*- FS
21	2		*FRONT BUMPER SUPPORT - LH / RH	Cracked	71.00 FS	*56.80 FS
22	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	106.00 FS	*- FS
23	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	130.00 FS	*- FS
24	1		*FRONT BUMPER TOP COVER	Deformed	149.00 FS	*118.80 FS
25	1		*AIR CONDITIONER STICKER	Necessary	36.00 FS	*28.64 FS
26	1		*CAUTION SIGN STICKER	Necessary	17.00 FS	*13.28 FS
27	1		*HORN LOW TONE - LH	Not Necessary	244.00 FS	*- FS
28	1		*HORN HIGH TONE - RH	Not Necessary	157.00 FS	*- FS
29	2		*HORN BRACKET - LH / RH	Not Necessary	112.00 FS	*- FS
30	2		*FRONT FENDER - LH / RH	Not Necessary	3,492.00 FS	*- FS
31	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	292.00 FS	*- FS
32	2		*FRONT FENDER BRACKET - LH / RH UPPER	Not Necessary	104.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	644.00 FS	*- FS
34	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	392.00 FS	*- FS
35	2		*FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH	Not Necessary	120.00 FS	*- FS
36	2		*FRONT WHEEL SPOILER TRIM BRACKET - LH / RH	Not Necessary	96.00 FS	*- FS
37	2		*BONNET HOOD SEAL COVER - LH / RH	Not Necessary	84.00 FS	*- FS
38	2		*BONNET LOCK COVER - LH / RH	Cracked	104.00 FS	*82.40 FS
39	1		*BONNET	Bent	5,971.00 FS	*4,776.80 FS
40	2		*BONNET HINGE - LH / RH	Bent	406.00 FS	*324.80 FS
41	1		*BONNET ATTACHMENT PARTS	Not Necessary	259.00 FS	*- FS
42	3		*BONNET IMPACT PROTECTION - LH / RH / CENTER	Necessary	99.00 FS	*78.48 FS
43	2		*BONNET STRIKER - LH / RH	Bent	260.00 FS	*208.00 FS
44	2		*BONNET LOCK - LH / RH	Not Necessary	488.00 FS	*- FS
45	1		*BONNET RELEASE ELEMENT	Bent	69.00 FS	*54.80 FS
46	1		*BONNET RELEASE LEVER	Cut	16.00 FS	*12.16 FS
47	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	67.00 FS	*- FS
48	1		*BONNET RELEASE CABLE COVER	Not Necessary	12.00 FS	*- FS
49	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	280.00 FS	*223.20 FS
50	2		*HEADLIGHT - LH / RH	Cracked	19,424.00 FS	*15,539.20 FS
51	2		*HEADLIGHT HOSE - LH / RH	Not Necessary	68.00 FS	*- FS
52	2		*LIFT CYLINDER - LH / RH	Not Necessary	460.00 FS	*- FS
53	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	16.00 FS	*- FS
54	1		*LIFT CYLINDER HOSE	Not Necessary	208.00 FS	*- FS
55	1		*LOCK CARRIER	Cracked	1,448.00 FS	*1,158.40 FS
56	2		*LOCK CARRIER SUPPORT - LH / RH	Not Necessary	52.00 FS	*- FS
57	1		*CHARGE AIR COOLER	Bent	692.00 FS	*553.60 FS
58	1		*CHARGE AIR COOLER PRESSURE HOSE - RH	Not Necessary	354.00 FS	*- FS
59	1		*CHARGE AIR COOLER PRESSURE PIPE - LH	Not Necessary	434.00 FS	*- FS
60	1		*A/C CONDENSER WITH DRYER	Bent	724.00 FS	*578.80 FS
61	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	293.00 FS	*- FS
62	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	312.00 FS	*- FS
63	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	293.00 FS	*- FS
64	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	27.00 FS	*- FS
65	1		*RADIATOR	Bent	1,103.00 FS	*882.40 FS
66	6		*READY-MIX COOLANT	Necessary	326.00 FS	*260.16 FS
67	1		*RADIATOR FAN RING	Not Necessary	318.00 FS	*- FS
68	1		*RADIATOR FAN WITH CONTROL UNIT	Scratched	2,131.00 FS	*1,704.80 FS
69	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	100.00 FS	*79.68 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
70	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	78.00 FS	*- FS
71	1		*RADIATOR INTAKE AIR DUCT	Not Necessary	54.00 FS	*- FS
72	1		*RADIATOR INTAKE AIR DUCT	Not Necessary	98.00 FS	*- FS
73	1		*RADIATOR AIR FILTER	Not Necessary	348.00 FS	*- FS
74	1		*RADIATOR INTAKE HOSE	Not Necessary	180.00 FS	*- FS
75	1		*AIS MASS METER	Not Necessary	639.00 FS	*- FS
76	2		*FRONT WATER DEFLECTOR STRIP - LH / RH	Not Necessary	140.00 FS	*- FS
77	2		*FRONT WINDOW GUIDE CHROME TRIM STRIP - LH / RH	Not Necessary	608.00 FS	*- FS
78	2		*FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH / RH OUTER	Not Necessary	474.00 FS	*- FS
79	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*60.00 FS
80	1		*SUNDRIES	Necessary	500.00 FS	*28.56 FS
81	1		*CAMERA (Supplementary)	Scratched	1,115.00 FS	*892.00 FS
82	1		*COOLANT PIPE (Supplementary)	Cracked	44.40 FS	*35.52 FS
83	1		*UPPER CLOSING ELEMENT (Supplementary)	Not Necessary	262.50 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	60,150.90 32,927.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	2,500.00
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS	New	7,500.00	1,260.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO CARRY OUT CALIBRATION FOR FRONT BUMPER CAMERA, DISTANCE REGULATION AND RADAR SENSOR (Supplementary)	New	480.00	480.00
Gross Labour Cost (\$\$)			19,212.00	8,212.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >