

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23001333/RNY3E2**Date:** 17/04/2023**REFERENCE**

Insured/Claimant:	MANJA HABIB	Policy No:	SP2002150947-01		
Date of Loss:	04/02/2023	Nature of Claim:	OD	Claim No:	202332005147

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7221Z		Engine No:	CJS308755
Make & Model:	VOLKSWAGEN PASSAT, 1.4 TSI (B7) (A)		Chassis No:	WVWZZZ3CZKE135542
Reg. Date:	15/07/2020 (Man. Year: 2019)		Odometer:	53331 km
Colour:	Black			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	S\$126,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,728.74	3,606.78	1,121.96	23.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	2,940.00	1,650.00	35.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,318.74	6,546.78	2,771.96	29.75
+ GST 8.00/8.00% (S\$)	745.50	523.74	221.76	29.75
Nett Amount (S\$)	10,064.24	7,070.52	2,993.72	29.75

INSPECTION

Date of Assignment:	07/02/2023		
Date Inspected:	10/02/2023	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts: 143	VOLKSWAGEN PASSAT 1.4 TSI (B7) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMT7221Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HOOD	Bent	1,308.25 FS	*1,308.25 FS
2	1	*COVER FOR BUMPER PRIMED	Deformed	1,380.97 FS	*1,380.97 FS
3	1	*LICENSE PLATE BRACKET SAT	Scratched	89.97 FS	*89.97 FS
4	1	*RIVET (4PCS)	Necessary	1.38 FS	*1.38 FS
5	1	*FOAM INSERT	Not Necessary	102.33 FS	*- FS
6	1	*IMPACT BEAM REINFORCEMENT	Not Necessary	741.78 FS	*- FS
7	1	*GUIDE PIECE BUMPER CTR BRACKET	Cracked	71.04 FS	*71.04 FS
8	1	*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	43.91 FS	*- FS
9	1	*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	44.31 FS	*- FS
10	1	*SET SENSOR BRACKETS	Necessary	38.40 FS	*38.40 FS
11	1	*RADIATOR GRILLE SATIN BLA	Cracked	495.16 FS	*495.16 FS
12	1	*VW SIGN BLACK / BRIGHT CHRO	Missing	76.84 FS	*76.84 FS
13	1	*SUPPORT FOR LOCK CARRIER	Cracked	29.40 FS	*29.40 FS
14	1	*VENT GRILLE WITH TRIM STR BUMPER CTR LOWER GRILLE	Not Necessary	189.63 FS	*- FS
15	1	*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
16	1	*AIR DUCT AIR GUIDE UPPER	Cracked	35.37 FS	*35.37 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 4,728.74 3,606.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,240.00	1,120.00
4	SPRAY PAINT	New	1,590.00	1,060.00
			Gross Labour Cost (\$\$)	4,590.00
				2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >