

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23001336/KQY3E2**Date:** 22/05/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 20/01/2023

Nature of Claim: OD

Claim No: MFL2023D0000788

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN7135X**
 Make & Model: MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A) Engine No: P520624891
 Reg. Date: 26/08/2019 (Man. Year: 2019) Chassis No: JM6BP2SAAK1101508
 Colour: Metallic Red Odometer: 40295 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: S\$92,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R18 Rear Tyre Size: 215/45 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,676.80	3,093.20	583.60	15.87
Miscellaneous Items	96.00	61.00	35.00	36.46
Labour	1,500.00	820.00	680.00	45.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,272.80	3,974.20	1,298.60	24.63
- Excess (\$\$)	0.00	750.00	-750.00	
(\$\$)	5,272.80	3,224.20	2,048.60	38.85
+ GST 8.00/8.00% (\$\$)	421.83	257.94	163.89	38.85
Nett Amount (\$\$)	5,694.63	3,482.14	2,212.49	38.85

INSPECTION

Date of Assignment: 08/02/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 09/02/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
Parts:	143	MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN7135X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	867.30 FL	*867.30 FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	20.50 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Distorted	20.50 FL	*20.50 FL
4	1		*FRONT RADIATOR GRILLE	Cracked	163.10 FL	*163.10 FL
5	1		*FRONT RADIATOR GRILLE CHROME LH	Cracked	298.00 FL	*298.00 FL
6	1		*FRONT RADIATOR GRILLE CHROME RH	Cracked	298.00 FL	*298.00 FL
7	1		*FRONT BONNET	Bent	1,040.80 FL	*1,040.80 FL
8	1		*FRONT BONNET RUBBER	Serviceable	55.90 FL	*- FL
9	1		*FRONT EMBLEM MAZDA	Dented / Scratched	707.90 FL	*54.80 FL
10	1		*FRONT NUMBER PLATE BASE	Cracked	77.00 FL	*77.00 FL
11	1		*FRONT NUMBER PLATE W/ CASING	Broken	45.00 FL	*45.00 FL
Supplementary #1						
12	1		*FRONT BUMPER TOP PANEL	Bent	140.00 FL	*140.00 FL
13	1		*FRONT BUMPER BAR PLASTIC	Cracked	88.00 FL	*88.00 FL
14	1		*FRONT BUMPER BAR METAL	Distorted	542.00 FL	*542.00 FL
15	1		*FRONT BUMPER LH AIR VENT	Dented	136.00 FL	*136.00 FL
16	1		*FRONT BUMPER INNER TYPE A	Cracked	40.00 FL	*40.00 FL
17	1		*FRONT BUMPER RIVET TYPE B	Necessary	20.00 FL	*20.00 FL
18	1		*FRONT PARKING SENSOR LH HOLDER	Necessary	18.00 FL	*18.00 FL
19	1		*FRONT PARKING SENSOR RH HOLDER	Necessary	18.00 FL	*18.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,596.00	3,866.50
- List Item Discount on L Items 20.00/20.00% (S\$)	919.20	773.30
Total Parts (S\$)	3,676.80	3,093.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Supplementary #1				
3	1	FRONT NUMBER PLATE (REPEATED)	35.00	0.00
Sub Total (\$\$)			96.00	61.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	800.00	400.00
2	To putty & respray on Front damage area.	New	650.00	400.00
3	To check wiring & focus headlamp	New	50.00	20.00
Gross Labour Cost (\$\$)			1,500.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >