

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG23001339/KQY3E2**Date:** 17/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001426328
Claimant Vehicle No :	SMU7162E	Insured Vehicle No :	SLQ9228U
Date of Loss:	14/01/2023	Nature of Claim:	TP
		Claim No:	299934

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7162E		
Make & Model:	MAZDA 3, 1.5 4DR M-HYBRID CLASSIC (A)	Engine No:	P520630282
Reg. Date:	26/08/2020 (Man. Year: 2019)	Chassis No:	JM6BP2SAAK1102151
Colour:	Metallic Black	Odometer:	41103 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,282.56	3,162.14	120.42	3.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	750.00	410.00	35.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,442.56	3,912.14	530.42	11.94
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,442.56	3,100.00	1,342.56	30.22
+ GST 8.00/8.00% (S\$)	355.40	248.00	107.40	30.22
Nett Amount (S\$)	4,797.96	3,348.00	1,449.96	30.22

INSPECTION

Date of Assignment:	08/02/2023	
Date Inspected:	08/02/2023	Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7162E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	994.30 FL	*867.30 FL
2	1		*FRT BUMPER RETAINER - LH	Serviceable	23.52 FL	*- FL
3	1		*FRT FENDER - LH	Buckled	476.81 FL	*476.81 FL
4	1		*FRT HEADLAMP - LH	Cut	2,266.62 FL	*2,266.62 FL
5	1		*FRT GRILLE (CHROME) - L/H	Cut	341.95 FL	*341.95 FL
					Sub Total (\$\$)	4,103.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	820.64
					Total Parts (\$\$)	3,282.56
						3,162.14

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL, KNOCK ON FRT ACCIDENT PORTION & CHANGE THE ABOVE PARTS	New	480.00	350.00
2	TO SPRAY PAINT ON FRT ACCIDENT PORTION	New	680.00	400.00
Gross Labour Cost (S\$)			1,160.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >