

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001342/SPA3Q2**Date:** 30/03/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SHC436R**Insured Vehicle No :** GBF9285E

Date of Loss: 07/02/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC436R**

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A)

Engine No: G4LEJU188476

Reg. Date: 02/04/2019 (Man. Year: 2018)

Chassis No: KMHC851CVKU140667

Colour: Yellow

Odometer: 532918 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,742.32	1,421.04	321.28	18.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	600.00	370.00	38.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,712.32	2,021.04	691.28	25.49
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	2,712.32	1,600.00	1,112.32	41.01
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 08/02/2023

Date Inspected: 09/02/2023 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC436R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	459.40 FL	*459.40 FL
2	1		*REAR BUMPER SIDE BRACKER RH	Not Necessary	55.80 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
5	2		*REAR BUMPER REINFORCEMENT STAY RH	Broken	138.10 FL	*138.10 FL
6	1		*REAR BUMPER FOG LAMP	Broken	201.50 FL	*201.50 FL
7	1		*TOWING COVER	Not Necessary	98.80 FL	*- FL
8	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
9	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
10	1		*REAR NUMBER PLATE W/HOLDER	Broken	55.00 FS	*55.00 FS
11	1		*REAR REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,106.65 1,750.05
					- List Item Discount on L Items 20.00/20.00% (\$\$)	364.33 329.01
					Total Parts (\$\$)	1,742.32 1,421.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	TUFF KOTE	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	0.00
Gross Labour Cost (\$\$)			970.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >