

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN			Ref:	CS3/LPC23001348/Wvy3m4
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	07/03/2023
			(Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YP 6938A	Veh. Inspected		SMK 1458U
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/23/23/VC05/026884	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		07/02/2023
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c		1794
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	JTDER12WX03003120	Colour		WHITE
	Odometer	238419 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/45 R17	ROTALLA		6 mm
	L/H Front Tyre	215/45 R17	ROTALLA		6 mm
	R/H Rear Tyre	215/45 R17	ROTALLA		6 mm
	L/H Rear Tyre	215/45 R17	ROTALLA		6 mm
4. Description of Damages					
	THE VEHICLE SUS	E SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information					
	Accident Date	24/01/2023	Inspect Date / T	ime	08/02/2023 (05:54 PM)
	Survey held at	AUBURN AUTO PTE LTD			
		176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED BY EASE FIND DAMAGED VEHICLE PHOTOGRAPHS				

Report Ref No. CS3/LPC23001348/Wvy3m4

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

DECD Anto Computer OAE Universal America

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$