

ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle Inspection Report

To:

Jovial Limo Services

C/o:

160 Sin Ming Drive #05-20

Sin Ming AutoCity (S) 575722

Date of request: Date of inspection:

Date of report:

19.03.2023 07.02.2023

07.02.2023

Date of accident:

03.02.2023

Report No: AAS/2023/015

Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no: Make/Model:

SM[9637Y

Toyota Vellfire (A)

Odometer: **Engine Capacity:** 184137 km 2493 cc

Year of registration:

2018/19

Engine no:

2AR1228306

Colour:

Metallic Black

Chassis no:

AGH300221317

Condition of tires:

Front Left:

Make:

6mm Habilead Front Right:

6mm Habilead

Rear Left: 6mm Make:

Habilead

Rear Right: Make:

Make:

6mm Habilead

Type of road wheel:

Alloy

(The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork

Handbrake Footbrake

Paintwork

: In order : In order : In order

: Good

: Good

Steering Apparent engine modification

: Nil

The Assignment

The inspection was conduct at M/s.

Lim Motor Pte Ltd

160 Sin Ming Drive #05-20 Sin Ming AutoCity (S) 575722

<u>Assessment</u>

Repairer's estimate:

7,524.35

Revised estimate:

6,623.43

Recommended reserve:

5,300.00 (Lump sum)

Estimated normal duration of repairs: 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMJ9637Y

Report No: AAS/2023/015

W/O PREJUDICE

Point of impact

At the LHS rear portion.

General description of damages

The LH sliding door, LHR quarter panel, rear bumper, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lim Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$6,623.43

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$5,300.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of $\underline{8}$ working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 21 photographs.

Your Faithfully Absolute Appraisal Services Pte Ltd





ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMJ9637Y					Report No: AAS/2023/015			
	raisement Schedule						·	
S/N	Parts Description	Qty	Condition		Rei	oairer's Est	Rev	vised Est
1	Sliding door LH	1	Dented		\$	2,856.80	\$	2,856.80
2	Sliding door weather seal with sensor LH	1	Necessary		\$	971.45	\$ \$	971.45 -
3	Sliding door lower weather seal LH	1	Necessary		\$	136.25	\$	136.25
4	Rear fender LH	1	Dented/Distorted		\$	1,613.40	\$	1,613.40
5	Rear bumper cover LH	1	Grazed/Repair		\$	307.90		**
6	Rear bumper		Grazed/Repair			-		-
				Total:	\$	5,885.80	\$	5,577.90
				-25%	\$	1,471.45	\$	1,394.48
				List total:	\$	4,414.35	\$	4,183.43
1	RHR quarter glass sealant	1	Necessary		\$	60.00	\$	40.00
				Special nett total:	\$	60.00	\$	40.00
				Parts Total:	\$	4,474.35	\$	4,223.43
S/N Labour Description					Repairer's Est		Re	vised Est
1	Check lightings & wirings.				\$	50.00	\$	30.00
2	Remove & transfer LH sliding do	or fitti	ngs.		\$	150.00	\$	100.00
3	3 Remove & reinstall rear trimmings, rear row seats, etc.				\$	200.00	\$	150.00
4 Remove & transfer LHR quarter glass.				\$	150.00	\$	120.00	
5	5 Remove & refit fuel tank to make way for replacement.				\$	150.00	\$	120.00
6	Rust proofing on affected & replacement panels.				\$	100.00	\$	30.00
7	Spray painting on affected & rep	olaceme	ent panels.		\$	1,000.00	\$	850.00
8	Conduct panel beating, straightening, cutting & reforming. Renew damaged parts. Re-align all affected area.				\$	1,250.00	\$	1,000.00
	· ·			Labour Total:	\$	3,050.00	\$	2,400.00
The	e final adjusted lump sum amount	is	\$5,300.00	Grand Total:	\$	7,524.35	\$	6,623.43

The final adjusted lump sum amount is \$5,300.00

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

21 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.













