

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9637Y

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                   |
| 1   | SLIDING DOOR LH  | DENTED                  | 2,856.80                      | 1,872.60          |
| 1   | SLIDING DOOR WEATHER SEAL WITH SENSOR LH   | NOT NECESSARY           | 971.45                        | -                 |
| 1   | SLIDING DOOR LOWER WEATHER SEAL LH   | NECESSARY               | 136.25                        | 136.25            |
| 1   | REAR FENDER LH   | TO REPAIR SEE<br>LABOUR | 1,613.40                      | -                 |
| 1   | REAR BUMPER COVER LH   | TO REPAIR SEE<br>LABOUR | 307.90                        | -                 |
| 1   | REAR BUMPER (NPA)  | TO REPAIR SEE<br>LABOUR | -                             | -                 |
|     | LESS 25% DISCOUNT  |                         | -1,471.45                     | -502.21           |
|     |  |                         | 4,414.35                      | 1,506.64          |
|     | SPECIAL NETT ITEMS   |                         |                               |                   |
| 1   | RHR QUARTER GLASS SEALANT (SN)   | NOT NECESSARY           | 60.00                         | -                 |
|     |  |                         | 60.00                         | -                 |
|     | <u>LABOUR</u>  |                         |                               |                   |
|     | CHECK LIGHTINGS & WIRINGS.   |                         | 50.00                         | 30.00             |
|     | REMOVE & TRANSFER LH SLIDING DOOR FITTINGS.  |                         | 150.00                        | 60.00             |
|     | REMOVE & REINSTALL REAR TRIMMINGS, REAR ROW SEAT, ETC.   |                         | 200.00                        | 60.00             |
|     | REMOVE & TRANSFER LHR QUARTER GLASS.   | NOT NECESSARY           | 150.00                        | -                 |
|     | REMOVE & REFIT FUEL TANK TO MAKE WAY FOR REPLACEMENT.  |                         | 150.00                        | 60.00             |
|     | RUST PROOFING ON AFFECTED & REPLACEMENT PANELS.  |                         | 100.00                        | 30.00             |
|     | SPRAY PAINTING ON AFFECTED & REPLACEMENT PANELS.   |                         | 1,000.00                      | 800.00            |
|     | CONDUCT PANEL BEATING, STRAIGHTENING, CUTTING & REFORMING. RENEW DAMAGED PARTS. RE-ALIGN ALL AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR FENDER LH, REAR BUMPER COVER LH AND REAR BUMPER. |                         | 1,250.00                      | 700.00            |
|     |  |                         | 3,050.00                      | 1,740.00          |
|     | GRAND TOTAL  |                         | 7,524.35                      | 3,246.64          |

Report Ref No. CS3/SMR23001349/Tqy3m4



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 2,600.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  |          |

Report Ref No. CS3/SMR23001349/Tqy3m4

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.