



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle Inspection Report

To: Jovial Limo Services
C/o: 160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

Date of report: 19.03.2023
Date of request: 07.02.2023
Date of inspection: 07.02.2023
Date of accident: 03.02.2023
Claim type: Third Party Claim

Report No: AAS/2023/015

Particulars of affected vehicle:

Registration no: SMJ9637Y
Make/Model: Toyota Vellfire (A)
Year of registration: 2018/19
Colour: Metallic Black

Odometer: 184137 km
Engine Capacity: 2493 cc
Engine no: 2ARJ228306
Chassis no: AGH300221317

Condition of tires:

Front Left: 6mm
Make: Habilead
Rear Left: 6mm
Make: Habilead

Front Right: 6mm
Make: Habilead
Rear Right: 6mm
Make: Habilead

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conduct at M/s. Lim Motor Pte Ltd
160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

Assessment

Repairer's estimate: \$ 7,524.35
Revised estimate: \$ 6,623.43
Recommended reserve: \$ 5,300.00 (Lump sum)

Estimated normal duration of repairs : 8 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMJ9637Y

Report No: AAS/2023/015

W/O PREJUDICE

Point of impact

At the LHS rear portion.

General description of damages

The LH sliding door, LHR quarter panel, rear bumper, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lim Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$6,623.43

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$5,300.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 8 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 21 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722

Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SMJ9637Y

Report No: AAS/2023/015

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Sliding door LH	1	Dented	\$ 2,856.80	\$ 2,856.80 1872.60
2	Sliding door weather seal with sensor LH	1	Necessary	\$ 971.45	\$ 971.45 XNN
					\$ -
3	Sliding door lower weather seal LH	1	Necessary	\$ 136.25	\$ 136.25
4	Rear fender LH	1	Dented/Distorted	\$ 1,613.40	\$ 1,613.40 XR
5	Rear bumper cover LH	1	Grazed/Repair	\$ 307.90	-
6	Rear bumper		Grazed/Repair	-	-

Total:	\$ 5,885.80	\$ 5,577.90 2008.85
-25%	\$ 1,471.45	\$ 1,394.48 1506.64
List total:	\$ 4,414.35	\$ 4,183.43

1	RHR quarter glass sealant	1	Necessary	\$ 60.00	\$ 40.00 XNN
---	---------------------------	---	-----------	----------	--------------

Special nett total:	\$ 60.00	\$ 40.00
---------------------	----------	----------

Parts Total:	\$ 4,474.35	\$ 4,223.43
--------------	-------------	-------------

S/N	Labour Description	Repairer's Est	Revised Est
1	Check lightings & wirings.	\$ 50.00	\$ 30.00
2	Remove & transfer LH sliding door fittings.	\$ 150.00	\$ 100.00 60
3	Remove & reinstall rear trimmings, rear row seats, etc.	\$ 200.00	\$ 150.00 60
4	Remove & transfer LHR quarter glass.	\$ 150.00	\$ 120.00 XNN
5	Remove & refit fuel tank to make way for replacement.	\$ 150.00	\$ 120.00 60
6	Rust proofing on affected & replacement panels.	\$ 100.00	\$ 30.00
7	Spray painting on affected & replacement panels.	\$ 1,000.00	\$ 850.00 800
8	Conduct panel beating, straightening, cutting & reforming. Renew damaged parts. Re-align all affected area.	\$ 1,250.00	\$ 1,000.00 700
Labour Total:		\$ 3,050.00	\$ 2,400.00 1740

Grand Total:	\$ 7,524.35	\$ 6,623.43
--------------	-------------	-------------

The final adjusted lump sum amount is \$5,300.00

3246.64
L/\$2600
6 DAYS

Under normal circumstances, the repair should be completed within a reasonable period of 8 working days.

21 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.











