

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDA 6655T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	2,265.00	1,655.90
1	REAR BUMPER CENTRE	GRAZED	1,120.00	711.43
1	REAR BUMPER LOWER CHROME DIFFUSER	CRACKED	780.00	545.00
1	REAR BUMPER UNDER COVER	NOT NECESSARY	580.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	72.00	-
2	REAR BUMPER REFLECTORS @\$112.00	NOT NECESSARY	224.00	-
1	REAR BUMPER REINFORCEMENT	BENT	680.00	680.00
2	REAR BUMPER REINFORCEMENT BRACKETS	NOT NECESSARY	178.00	-
2	REAR BUMPER SIDE FRAME LH & RH	NOT NECESSARY	360.00	-
1	REAR BUMPER INNER SIDE BRACKETS	CRACKED	180.00	180.00
1	TAILGATE	TO REPAIR SEE LABOUR	2,562.00	-
1	TAILGATE CENTRE BADGE	NOT NECESSARY	74.00	-
1	TAILGATE C&C EMBLEM PLATE	NOT NECESSARY	72.00	-
1	TAILGATE GLC 200 EMBLEM	NOT NECESSARY	98.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	328.00	-
1	TAILGATE INNER BOARD (NPA) (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER REFLECTOR LAMP (NPA)	NOT NECESSARY	-	-
1	TAILGATE INNER LOCK AUTO MECHANISM (NPA)	NOT NECESSARY	-	-
1	REAR BOOT EDGE WEATHERSTRIP	NOT NECESSARY	198.00	-
1	TAILGATE TOP SPOILER (NPA)	NOT NECESSARY	-	-
2	TAILGATE NUMBER PLATE LAMP (NPA)	NOT NECESSARY	-	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	750.00	-
1	REAR END PANEL OUTER TOP GARNISH	NOT NECESSARY	290.00	-
2	REAR END PANEL TOP GARNISH CHROME MAT	NOT NECESSARY	250.00	-
1	REAR EXHAUST SILENCER ASSEMBLY	NOT NECESSARY	1,980.00	-
2	REAR EXHAUST PIPE END CHROME @\$210.00	NOT NECESSARY	420.00	-
8	REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	NOT NECESSARY	192.00	-
	LESS 10% DISCOUNT		-1,365.30	-377.23
			12,287.70	3,395.10

Report Ref No. CS/SMO23001351/Uqy3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	TAILGATE INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSORS WIRING HARNESS (SN)	NOT NECESSARY	150.00	-
1	REVERSE SENSORS (SN)	SHORTED	380.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	REAR WINDSCREEN RUBBER (SN)	NOT NECESSARY	280.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	50.00
			1,170.00	250.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL .		1,200.00	550.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,000.00	680.00
	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION		150.00	20.00
	TO REMOVE/REFIX INNER TRIMS ,FITTINGS,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR .		150.00	60.00
	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATION .	NOT NECESSARY	250.00	-
	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION .		150.00	50.00
	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSY AND REALIGN TO FIT AND CHECK FOR SYSTEM FUNCTION.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
			3,390.00	1,360.00
	GRAND TOTAL		16,847.70	5,005.10

Report Ref No. CS/SMO23001351/Uqy3q2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	4,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO23001351/Uqy3q2

CHUA KANG SENG

**Licensed Appraiser**