

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMO 2300135114943

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDA 66557

at Workshop m/s 2nd Ave

of _____

Insured: SLX 9808J

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 130k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 8536 Vehicle: IN / OUT

Date / Time Action / Instruction 29/11/13

Veh No: SDA 66557 Yr Regn: 18/04/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA

Make: Mercedes Benz GLC 200c 1991

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 4835-7 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC 2539422F 391761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 25/01/23

Survey held at _____

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 8/2/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1/5/2 10:54

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum / I.B.I. (\$) 4000

15/2/23 1/5 \$ 4000 in hand AH long (Paid \$ 12847, 76%)

not allowed
new

8/12/23

Page No. 1

1/5 R 4000/

4 days

VEHICLE NO. SDA 6655T

MERCEDES BENZ GLC200

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear Bumper <i>20/12</i>		2265.00	1655.50
1	Rear Bumper centre <i>gross</i>		1120.00	711.43
1	Rear Bumper lower chrome diffuser <i>Cre</i>		780.00	545.00
1	Rear Bumper under cover <i>11</i>		580.00	X
1	Rear Bumper tow cover <i>11</i>		72.00	X
2	Rear Bumper reflectors \$112 <i>11</i>		224.00	X
1	Rear Bumper Reinforcement <i>3uf</i>		680.00	/
2	Rear Bumper Reinforcement Brackets <i>11</i>		178.00	X
2	Rear Bumper Side Frame LH & RH <i>11</i>		360.00	X
2/1	Rear Bumper inner side brackets <i>Cre</i>		180.00	/
1	Tailgate <i>2</i>		2562.00	X
1	Tailgate centre badge <i>11</i>		74.00	X
1	Tailgate C&C emblem plate <i>11</i>		72.00	X
1	Tailgate GLC 200 emblem <i>11</i>		98.00	X
1	Tailgate inner lock <i>11</i>		328.00	X
1	Tailgate inner board <i>11</i>	REFIX	0.00	X
1	Tailgate inner reflector lamp <i>11</i>	REFIX	0.00	X
1	Tailgate Inner Lock Auto mechanism <i>11</i>	REFIX	0.00	X
1	Rear Boot Edge Weatherstrip <i>11</i>		198.00	X
1	Tailgate top spoiler <i>11</i>	REFIX	0.00	X
2	Tailgate number plate lamp <i>11</i>	REFIX	0.00	X
1	Rear End panel <i>2</i>		750.00	X
1	Rear end panel outer top garnish <i>11</i>		290.00	X
2	Rear end panel top garnish chrome mat <i>11</i>		250.00	X
1	Rear exhaust silencer assembly <i>11</i>		1980.00	X
2	Rear Exhaust pipe end chrome @\$210 <i>11</i>		420.00	X
8	Rear exhaust silencer assembly mountings <i>11</i>		192.00	X
			13653.00	
less 10%			1365.30	10%
			12287.70	
SPECIAL NETT ITEMS				
1	Tailgate Inner Trim Clips <i>11</i>		80.00	X
1	Reverse Sensors wiring harness <i>11</i>		150.00	X
1	Reverse Sensors <i>shut</i>		380.00	200
1	Rear windscreen sealant <i>11</i>		120.00	X
1	Rear windscreen rubber <i>11</i>		280.00	X
1	Rear end panel sealant <i>11</i>		100.00	X
1 set	Rear bumper clips <i>rec</i>		60.00	50
TOTAL PARTS			13457.70	

VEHICLE NO. SDA 6655T MERCEDES BENZ GLC200

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1200.00	550
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	680
3	To remove, refix wiring system at accident damaged areas and check for proper function	150.00	20
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00	60
5	To clear fault code with diagnostic computer and reset to specification	250.00	11 X
6	To remove and replace reverse sensors and check for proper function	150.00	50
7	To remove and replace rear exhaust silencer assy and realign to fit and check for system function	250.00	11 X
8	To remove and refix rear windscreen	120.00	11 X
9	To perform anti-rust treatment on affected areas	120.00	11 X
	Labour Total :	3390.00	
	TOTAL (PARTS & LABOUR):	16847.00	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

PRELIMINARY ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2. 3772.33
102
3395.09
250
1362