

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23001353/ANCM4**Date:** 08/05/2023**REFERENCE**

Insured/Claimant:	CHEE OI CHOO	Policy No:	2100429549	
Date of Loss:	18/01/2023	Nature of Claim:	OD	Claim No: 7491787747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCV1312S		
Make & Model:	AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)	Engine No:	CZC283157
Reg. Date:	23/09/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8V9GA034778
Colour:	Silver	Odometer:	22695 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$51,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,378.00	5,411.20	6,966.80	56.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,542.00	2,740.00	51.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,660.00	7,953.20	9,706.80	54.96
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	17,060.00	7,353.20	9,706.80	56.90
+ GST 8.00/8.00% (\$\$)	1,364.80	588.26	776.54	56.90
Nett Amount (\$\$)	18,424.80	7,941.46	10,483.34	56.90

INSPECTION

Date of Assignment:	08/02/2023		
Date Inspected:	07/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,273.00 FS	*1,818.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	207.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	185.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	75.00 FS	*59.92 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE- RH	Not Necessary	129.00 FS	*- FS
6	1		*FRONT FENDER - RH	Dented	1,012.00 FS	*809.60 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	80.00 FS	*- FS
8	1		*FRONT FENDER CLOSING ELEMENT	Damaged	73.00 FS	*57.68 FS
9	1		*FRONT FENDER BRACKET - RH	Not Necessary	72.00 FS	*- FS
10	9		*FRONT FENDER RIVET	Necessary	36.00 FS	*28.80 FS
11	1		*FRONT FENDER BRACE	Bent	114.00 FS	*91.20 FS
12	1		*FRONT WHEEL HOUSING LINER	Deformed	198.00 FS	*158.00 FS
13	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	99.00 FS	*- FS
14	1		*HEADLIGHT GAS DISCHARGE LAMP - RH	Cracked	2,975.00 FS	*2,380.00 FS
15	1		*HEADLIGHT POWER MODULE	Not Necessary	690.00 FS	*- FS
16	1		*HEADLIGHT CONTROL UNIT	Not Necessary	1,390.00 FS	*- FS
17	1		*GAS DISCHARGE LAMP	Not Necessary	462.00 FS	*- FS
18	1		*HEADLIGHT HOSE - RH	Not Necessary	62.00 FS	*- FS
19	1		*LIFT CYLINDER - RH	Not Necessary	223.00 FS	*- FS
20	1		*LIFT CYLINDER HOSE	Not Necessary	208.00 FS	*- FS
21	1		*FRONT ALUMINIUM RIM	Not Necessary	1,411.00 FS	*- FS
22	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
23	1		*SUNDRIES	Necessary	400.00 FS	*7.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **12,378.00** **5,411.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,282.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >