

ASS. REC. BY:

REF:

HSB/ 230013601kp

0

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TB / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of mya 01-34 FORBS 5825

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8136k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SML 3999G Yr Regn: 01, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Kia Settas c.c. 1353

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 32073 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_ C/No: M8BEP811V6N123613

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 18/1/23 D.O.I. 20/2/2023

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/2 11 Rpt @ 3750k Cash

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: \_\_\_\_\_

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$)

Survey Fee:

: Interview (\$)

Transportation

: Tech Invs (\$)

S - RS. SI

: Weekend (\$)

Fixes

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



**FORZA AUTOHAUS PTE LTD**  
 39 WOODLANDS CLOSE, #01-34/35, MEGA@WOODLANDS  
 SINGAPORE 737856  
 TEL: 62781889 EMAIL: ENQUIRY@FORZAAUTO.SG  
 CO./GST REG: 201833292C

*Not Authorized  
 C1 Rep \$3250/h  
 Penning After Paint  
 5 days*

LOUIS LER  
 BLK 844 WOODLANDS AVE 4 #06-602  
 Singapore 730844  
 Contact No. : 98213455

Code : E23020003  
 Date In : 02/02/2023  
 Vehicle No. : SML3999G  
 Model : KIA, SELTOS 1.4 DCT  
 Chassis No. : MZBEP811VLN123613

**ESTIMATE**

**Parts and Labour Assessment**

Description	Qty	Unit Price	Amount
<b>Parts &amp; Services</b>			
REAR TRUNK TOP CARPET COVER BOARD	1.00	482.30	482.30 X
REAR END PANEL TOP GARNISH COVER	1.00	282.30	282.30 A
REAR END PANEL <i>762-10</i>	1.00	921.60	921.60 ✓
REAR TRUNK PANEL	1.00	1,321.40	1,321.40 X
REAR BUMPER TOW COVER	1.00	62.30	62.30 ✓
REAR BUMPER INNER REINFORCEMENT BEAM	1.00	425.30	425.30 ✓
REAR BUMPER LOWER DIFFUSER	1.00	372.30	372.30 ✓
REAR BUMPER RETAINER RH	1.00	152.30	152.30 ✓
REAR BUMPER	1.00	723.40	723.40 ✓
		Subtotal Before Discount S\$	4,743.20
		10.00% Discount S\$	474.32
		<b>Subtotal S\$</b>	<b>4,268.88</b>
REAR BUMPER REVERSE SENSOR SET	1.00	250.00	250.00 <i>Phon 2000A</i>
REAR BUMPER CLIPS SET	1.00	30.00	30.00 ✓
		<b>Subtotal S\$</b>	<b>280.00</b>
		<b>Parts &amp; Services Total S\$</b>	<b>4,548.88</b>
<b>Labour</b>			
TO REMOVE AND REINSTATE REAR TRUNK COMPONENT & TRIM	1.00	200.00	200.00 <i>601</i>
TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	1.00	100.00	100.00 <i>601</i>
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	1.00	1,500.00	1,500.00 <i>800</i>
TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1.00	1,200.00	1,200.00 <i>700</i>
		<b>Subtotal S\$</b>	<b>3,000.00</b>
		<b>Labour Total S\$</b>	<b>3,000.00</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

**Parts & Services Total S\$ 4,548.88**  
**Labour Total S\$ 3,000.00**  
**Grand Total S\$ 7,548.88**