

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23001365/HVY3E2**Date:** 06/04/2023**REFERENCE**

Insured/Claimant:	DONOVAN EU KUM CHUEN	Policy No:	SP2002093149-01
Date of Loss:	03/02/2023	Nature of Claim:	OD
		Claim No:	202332005142

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMH2079P</b>		
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Engine No:	8ARZ145724
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	JTEZB3GH50J003772
Colour:	Red	Odometer:	9967 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,179.70	2,594.90	1,584.80	37.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,480.00	910.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,569.70</b>	<b>4,074.90</b>	<b>2,494.80</b>	<b>37.97</b>
<b>- Excess (S\$)</b>	0.00	600.00	-600.00	
<b>(S\$)</b>	6,569.70	3,474.90	3,094.80	47.11
<b>+ GST 8.00/8.00% (S\$)</b>	525.58	277.99	247.59	47.11
<b>Nett Amount (S\$)</b>	<b>7,095.28</b>	<b>3,752.89</b>	<b>3,342.39</b>	<b>47.11</b>

**INSPECTION**

Date of Assignment:	09/02/2023	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	09/02/2023	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	4.0 days		

**Adjuster:** Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2023)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH2079P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*TAILGATE</b> (WCP)	Dented	780.00 F	*780.00 F
2	1		<b>*TAILGATE GLASS MOULDING</b> (WCP)	Necessary	120.00 F	*120.00 F
3	1		<b>*TAILGATE GLASS SEALANT</b> (WCP)	Not Necessary	40.00 FS	*- FS
4	1		<b>*TAILGATE REFLECTOR RH</b> (WCP)	Cut	230.00 F	*230.00 F
5	1		<b>*TAILGATE EMBLEM - HARRIER</b> (WCP)	Necessary	55.00 F	*55.00 F
6	1		<b>*TAILGATE EMBLEM - TURBO</b> (WCP)	Not Necessary	45.00 F	*- F
7	1		<b>*TAILGATE WEATHERSTRIP</b> (WCP)	Not Necessary	145.00 F	*- F
8	1		<b>*REAR FENDER RH</b> (WCP)	Repair	580.00 F	*- F
9	1		<b>*REAR QUARTER GLASS MOULDING GLASS RH</b> (WCP)	Not Necessary	580.00 F	*- F
10	1		<b>*REAR QUARTER GLASS SEALANT RH</b>	Not Necessary	40.00 FS	*- FS
11	1		<b>*TAILLAMP ASSY RH</b> (WCP)	Scratched	275.00 F	*275.00 F
12	2		<b>*TAILLAMP CLIPS</b> (WCP)	Necessary	14.00 F	*14.00 F
13	1		<b>*TAILLAMP PANEL RH - REPAIR</b> (NPA)	Repair	-	*- F
14	1		<b>*REAR BUMPER</b> (WCP)	Buckled	380.00 F	*380.00 F
15	1		<b>*REAR BUMPER LOWER GARNISH</b> (WCP)	Cut	260.00 F	*260.00 F
16	1		<b>*REAR BUMPER RETAINER RH</b> (WCP)	Not Necessary	18.00 F	*- F
17	10		<b>*REAR BUMPER CLIPS</b> (WCP)	Necessary	20.00 F	*20.00 F
18	1		<b>*REVERSE SENSOR RH</b> (WCP)	Missing	225.00 F	*225.00 F
19	1		<b>*REAR END PANEL - REPAIR</b> (NPA)	Repair	-	*- F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>3,807.00</b>	<b>2,359.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	372.70	235.90
<b>Total Parts (\$\$)</b>	<b>4,179.70</b>	<b>2,594.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CUT/ WELD REAR FENDER RH. KNOCK AND STRAIGHTEN TAILLAMP PANEL RH, REAR END PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	1,000.00	600.00
2	SPRAY PAINT TAILGATE, TAILLAMP PANEL RH, REAR END PANEL, REAR FENDER RH, REAR BUMPER	New	1,000.00	600.00
3	REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00	120.00
4	REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM	New	60.00	60.00
5	REMOVE & REAPLACE REAR FENDER INNER TRIM RH, GARNISH, UPHOLSTERY, REAR SEAT AND REAR FLOOR CARPET	New	150.00	60.00
6	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	60.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,390.00</b>	<b>1,480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >