

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23001366/AQCE2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	ANTHONY HING FAI MAN	Policy No:	1800020709	
Date of Loss:	04/01/2023	Nature of Claim:	OD	Claim No: 0555728610SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9126Z		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK050860
Reg. Date:	08/03/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF57JA049726
Colour:	White	Odometer:	44747 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,311.00	5,047.60	2,263.40	30.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,352.00	9,017.00	7,335.00	44.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,663.00	14,064.60	9,598.40	40.56
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	22,063.00	12,464.60	9,598.40	43.50
+ GST 8.00/8.00% (S\$)	1,765.04	997.17	767.87	43.50
Nett Amount (S\$)	23,828.04	13,461.77	10,366.27	43.50

INSPECTION

Date of Assignment:	08/02/2023		
Date Inspected:	07/02/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE PANEL - LH	Dented	4,315.00 FS	*3,452.00 FS
2	1		*REAR QUARTER WINDOW - LH	Necessary	844.00 FS	*675.20 FS
3	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	52.00 FS	*- FS
4	1		*REAR ATTACHMENT PARTS	Not Necessary	144.00 FS	*- FS
5	1		*REAR ADHESIVE TAPES	Not Necessary	230.00 FS	*- FS
6	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	322.00 FS	*- FS
7	1		*WINDOW PRIMER	Necessary	24.00 FS	*18.80 FS
8	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
9	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
10	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
11	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
12	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
13	1		*SUNDRIES	Necessary	500.00 FS	*21.60 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	7,311.00 5,047.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	0.00
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	300.00	300.00
3	TO INSTALL SOLAR FIM FOR ALL THE AFFECTED GLASSES	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,600.00	1,600.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
6	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES, AND REAR END PANELLING	New	5,500.00	1,925.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND REINSTALL LHS SILL PANEL TRIM AND REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
Gross Labour Cost (\$\$)			16,352.00	9,017.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >