



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1994P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	BROKEN	481.10	481.10
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT FENDER SHIELD LH	SERVICEABLE	164.70	-
1	FRT BUMPER SIDE BRACKET LH	SERVICEABLE	35.00	-
1	HEADLAMP ASSY LH	SCRATCHED	2,110.30	2,110.30
1	FRT FOG LAMP GRILLE LH	SERVICEABLE	93.45	-
1	FRT FOG LAMP LH	CUT	642.50	642.50
1	FRT FENDER LH	DENTED	588.80	588.80
1	FRT FENDER EMBLEM LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-832.89	-774.26
			3,331.56	3,097.04
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	525.00
	SPRAY PAINT.		600.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	20.00
			1,500.00	1,075.00
	GRAND TOTAL		4,831.56	4,172.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,350.00

Report Ref No. NS/INC23001368/Dwy3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.