

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23001380/Wqy3e2	
	60 WOODLANDS I E4SINGAPORE 75		Date:	16/02/2023		
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 1213R	Veh. Inspected	k	GBE 1257U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/02/23/2012	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		09/02/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JN1MC2E26Z0004381	Colour		WHITE	
	Odometer	312378 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		7 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		7 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE		7 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	5. General Information					
	Accident Date	05/02/2023	Inspect Date /	Time	09/02/2023 (03:12 PM)	
	Survey held at TEAM AUTOPRO PTE LTD					
	160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,600-\$4,600					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMR23001380/Wqy3e2

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser