

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123001385/AVP3E2
Date: 08/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00172912202
Claimant Vehicle No :	SMQ4259B	Insured Vehicle No :	SMH5477D
Date of Loss:	20/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200664/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4259B	Engine No:	G4FGKU475932
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMLU011658
Reg. Date:	15/11/2019 (Man. Year: 2019)	Odometer:	201741 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,238.88	8,469.52	6,769.36	44.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	2,210.00	1,480.00	40.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,928.88	10,679.52	8,249.36	43.58
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	18,928.88	8,500.00	10,428.88	55.10

INSPECTION

Date of Assignment:	09/02/2023		
Date Inspected:	30/01/2023	Inspected At:	Hiap Hong Motor Repair 2 Kaki Bykit Avenue 2, #02-13 Singapore 417921
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4259B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER SIDE HOLDER LH	Damaged	32.90 FL	*32.90 FL
3	1		*FRONT BUMPER FOG LAMP LH	Cracked	211.20 FL	*211.20 FL
4	1		*FRONT BUMPER FOG LAMP COVER LH	Damaged	110.40 FL	*110.40 FL
5	1		*FRONT BUMPER FOG LAMP LOWER MOULDING LH	Deformed	58.90 FL	*58.90 FL
6	1		*FRONT BUMPER INNER AIR DUCT LH	Deformed	45.90 FL	*45.90 FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	395.80 FL	*395.80 FL
8	1		*FRONT BUMPER LOWER STIFFENER	Not Necessary	175.20 FL	*- FL
9	1		*FRONT GRILLE	Cracked	529.90 FL	*529.90 FL
10	1		*FRONT GRILLE LOGO	Necessary	45.40 FL	*45.40 FL
11	1		*HEADLAMP LH	Cracked	1,811.40 FL	*1,811.40 FL
12	1		*HEADLAMP LOWER BRACKET LH	Cracked	58.40 FL	*58.40 FL
13	1		*BONNET	Not Necessary	1,741.20 FL	*- FL
14	1		*BONNET HINGE	Not Necessary	98.20 FL	*- FL
15	1		*BONNET LOCK	Not Necessary	75.80 FL	*- FL
16	1		*FRONT LH FENDER	Distorted	1,227.70 FL	*1,227.70 FL
17	1		*FRONT LH FENDER INNER SHIELD	Torn	145.80 FL	*145.80 FL
18	1		*FRONT LH FENDER MUDFLAP	Distorted	89.90 FL	*89.90 FL
19	1		*FRONT LH FENDER QUARTER GARNISH	Missing	45.30 FL	*45.30 FL
20	1		*FRONT LH FENDER BRACKET	Bent	65.10 FL	*65.10 FL
21	1		*FRONT LH DOOR	Repair	1,832.50 FL	*- FL
22	2		*FRONT LH DOOR HINGE	Not Necessary	84.40 FL	*- FL
23	1		*FRONT LH DOOR WING MIRROR ASSY	Damaged	638.60 FL	*638.60 FL
24	1		*FRONT LH SHOCK ABSORBER	Bent	372.50 FL	*372.50 FL
25	1		*FRONT LH KNUCKLE ARM	Damaged	451.10 FL	*451.10 FL
26	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	266.40 FL	*266.40 FL
27	1		*FRONT LH LOWER ARM	Bent	326.70 FL	*326.70 FL
28	1		*FRONT LH ANTI ROLL BAR LINKAGE	Bent	98.90 FL	*98.90 FL
29	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,030.70 FL	*- FL
30	1		*STEERING RACK & PINION	Bent	1,897.50 FL	*1,897.50 FL
31	1		*STEERING CROSS MEMBER	Not Necessary	1,803.90 FL	*- FL
32	1		*FRONT ANTI ROLL BAR	Not Necessary	345.80 FL	*- FL
33	1		*AIR RESONATOR TANK	Cracked	261.80 FL	*261.80 FL
34	1		*ENGINE UNDERCOVER	Not Necessary	286.50 FL	*- FL
35	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
36	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
38	1		*FRONT LH DOOR VISOR	Cut	80.00 FS	*60.00 FS
39	1		*FRONT LH DOOR BLACK TAPE	Not Necessary	60.00 FS	*- FS
40	1		*FRONT LH WHEEL RIM	Cut	1,000.00 FS	*600.00 FS
41	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS
42	1		*ENGINE UNDERCOVER CLIPS	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					18,666.10	10,401.90
- List Item Discount on L Items 20.00/20.00% (S\$)					3,427.22	1,932.38
Total Parts (S\$)					15,238.88	8,469.52
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	480.00	380.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO TRANSFER DOOR FITTINGS	New	150.00	0.00
8	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			3,690.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >