

HIAP HONG MOTOR REPAIR

2 KAKI BUKI AVENUE

#02-13 SINGAPORE 417921

Tp China.

Veron

Page No. 1

Vehicle No. SMQ4259B

HYUNDAI AVANTE

KMHD841CMLU011658

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Distorted</i>		474.40	✓
2	FRONT BUMPER SIDE HOLDER LH <i>Dmd</i>		32.90	✓
3	FRONT BUMPER FOG LAMP LH <i>cracked</i>		211.20	✓
4	FRONT BUMPER FOG LAMP COVER LH <i>Dmd</i>		110.40	✓
5	FRONT BUMPER FOG LAMP LOWER MOULDING LH <i>del d</i>		58.90	✓
6	FRONT BUMPER INNER AIR DUCT LH <i>del d</i>		45.90	✓
7	FRONT BUMPER REINFORCEMENT <i>Dented</i>		395.80	✓
8	FRONT BUMPER LOWER STIFFENER <i>Not new</i>		175.20	X
9	FRONT GRILLE <i>cracked</i>		529.90	✓
10	FRONT GRILLE LOGO <i>1 New</i>		45.40	✓
11	HEADLAMP LH <i>crack</i>		1811.40	✓
12	HEADLAMP LOWER BRACKET LH <i>cracked</i>		58.40	✓
13	BONNET <i>Not new</i>		1741.20	X
14	BONNET HINGE @49.10 <i>Not new</i>		98.20	X
15	BONNET LOCK <i>Not new</i>		75.80	X
16	FRONT LH FENDER <i>Distorted</i>		1227.70	✓
17	FRONT LH FENDER INNER SHIELD <i>torn</i>		145.80	✓
18	FRONT LH FENDER MUDFLAP <i>Distorted</i>		89.90	✓
19	FRONT LH FENDER QUARTER GARNISH <i>Missing</i>		45.30	✓
20	FRONT LH FENDER BRACKET <i>Bent</i>		65.10	✓
21	FRONT LH DOOR <i>Rep</i>		1832.50	X
22	FRONT LH DOOR HINGE @42.20 <i>Not new</i>		84.40	X
23	FRONT LH DOOR WING MIRROR ASSY <i>Damaged</i>		638.60	✓
24	FRONT LH SHOCK ABSORBER <i>Bent</i>		372.50	✓
25	FRONT LH KNUCKLE ARM <i>Dmd</i>		451.10	✓
26	FRONT LH WHEEL HUB C/W BEARING <i>Dmd</i>		266.40	✓
27	FRONT LH LOWER ARM <i>Bent</i>		326.70	✓
28	FRONT LH ANTI ROLL BAR LINKAGE <i>Bent</i>		98.90	✓
29	FRONT LH DRIVE SHAFT <i>Not new</i>		1030.70	X
30	STEERING RACK & PINION <i>Bent</i>		1897.50	✓
31	STEERING CROSS MEMBER <i>Not new</i>		1803.90	X
32	FRONT ANTI ROLL BAR <i>Not new</i>		345.80	X
33	AIR RESONATOR TANK <i>cracked</i>		261.80	✓
34	ENGINE UNDERCOVER <i>Not new</i>		286.50	X
			17136.10	
less 20%			3427.22	20%
			13708.88	
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS <i>new</i>		30.00	✓
2	FRONT GRILLE CLIPS <i>new</i>		20.00	✓
3	FRONT LH FENDER INNER SHIELD CLIPS <i>new</i>		30.00	✓
4	FRONT LH DOOR VISOR <i>lt</i>		80.00	60
5	FRONT LH DOOR BLACK TAPE <i>Not new</i>		60.00	X

9661.90
7729.52

6	FRONT LH WHEEL RIM	<i>cut</i>	1000.00	<i>500.</i>
7	FRONT LH TYRE	<i>Not new</i>	280.00	<i>X</i>
8	ENGINE UNDERCOVER CLIPS	<i>Not new</i>	30.00	<i>X</i>
Total Parts			1530.00	

740

HIAP HONG MOTOR REPAIR
2 KAKI BUKI AVENUE
#02-13 SINGAPORE 417921

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1400.00 800	
2	SPRAY PAINTING	1200.00 800	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	150.00 60	
5	TO DISMANTLE FRONT UNDERCARRIAGE	480.00 380	2150
6	TO PERFORM WHEEL ALIGNMENT	150.00 80	
7	TO TRANSFER DOOR FITTINGS	150.00 x	
8	TOWING FEES	60.00 ✓	
	Labour Total :	3690.00	
	TOTAL (PARTS & LABO	10065.36	

total 10619.52
 L/S: 8.5K.

10 Days.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: