

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT STRIDES AUTOMOTIVE SERVICES PTE LTD Ref: CS3/SMR23001394/Wvy3e2 60 WOODLANDS INDUSTRIAL PARK Date: 16/02/2023 E4SINGAPORE 757705 Code: SMR 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHB 5006X** SKW 9490H Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. TAX/02/23/2010 Excess (\$) 0.00 **HUA YEN Assign Date** 09/02/2023 Assign From **Vehicle Particulars & Condition** 2. MAZDA 3 1496 Make & Model C.C HIDDEN 2015 Engine No. Year of Reg. JM6BM42A8G0323521 SILVER Chassis No. Colour Odometer 207643 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/60 R16 **FARROAD** 6 mm **FARROAD** L/H Front Tyre 205/60 R16 6 mm 205/60 R16 **FARROAD** R/H Rear Tyre 6 mm **FARROAD** L/H Rear Tyre 205/60 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information** 03/02/2023 09/02/2023 (02:55 PM) Inspect Date / Time Accident Date **TEAM AUTOPRO PTE LTD** Survey held at 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,600-\$7,600

Report Ref No. CS3/SMR23001394/Wvy3e2

Estimate Days of Repair

Inspected By

Asst. Automotive Assessor

5b.

MUHAMMAD AKID BIN MOHAMED KAMAL

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

7 Working Days