




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SINGAPORE CIVIL DEFENCE FORCE (MHA05) 91 UBI AVE 4 SINGAPORE 408827 SINGAPORE 408827 ATTN: RALF TAY			Ref: CS3/SCD23001401/Kqy3e2 Date: 13/02/2023  Code: SCD			
1. Policy Particulars :- (THIRD PARTY CLAIM)						
Insured Veh.		QX 1275P	Veh. Inspected		FBJ 2519G	
Policy No.			Coverage (\$)		0.00	
Claim No.		2023 - 13	Excess (\$)		0.00	
Assign From		RALF TAY	Assign Date		09/02/2023	
2. Vehicle Particulars & Condition						
Make & Model		HONDA NC750XA	c.c		745	
Engine No.		HIDDEN	Year of Reg.		2014	
Chassis No.		JH2RC72B8EK001244	Colour		SILVER	
Odometer		78051 KM	Steering		IN ORDER	
Brakes		IN ORDER	Modification		STANDARD ALLOY RIM	
General		GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
	R/H Front Tyre	120/70Z R17	PIRELLI	2 mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre	160/60Z R17	PIRELLI	2 mm		
	L/H Rear Tyre			mm		
4. Description of Damages						
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.						
5. General Information						
Accident Date		07/02/2023	Inspect Date / Time			09/02/2023 ( 11:47 AM )
Survey held at		SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047				
5a. Remarks						
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000						
5b. Estimate Days of Repair						
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days			

Report Ref No. CS3/SCD23001401/Kqy3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FBJ 2519G

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

