



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 5152L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (N)	CUT	595.10	595.10
1	FRONT BUMPER SIDE RETAINER (LH) (N)	CRACKED	114.30	114.30
1	FRONT BUMPER REINFORCEMENT BEAM (N)	NOT NECESSARY	429.10	-
1	HEADLAMP LH (N)	CRACKED	718.20	718.20
1	FRONT DOOR LH (N)	TO REPAIR SEE LABOUR	1,406.10	-
1	FRONT DOOR HINGE LH (UPPER) (N)	NOT NECESSARY	74.10	-
1	FRONT DOOR HINGE LH (LOWER) (N)	NOT NECESSARY	74.10	-
1	FRONT DOOR CHECK LH (N)	NOT NECESSARY	120.10	-
1	FRONT DOOR LH STEP -UP GARNISH (N)	GRAZED	115.10	115.10
1	FRONT DOOR LH STEP -UP PANEL (N)	TO REPAIR SEE LABOUR	435.00	-
1	FRONT SHOCK ABSORBER LH (N)	NOT NECESSARY	325.90	-
1	FRONT WHEEL BEARING LH (N)	NOT NECESSARY	136.20	-
1	FRONT WHEEL HUB LH (N)	NOT NECESSARY	385.10	-
1	FRONT LOWER ARM LH (N)	NOT NECESSARY	149.20	-
1	FRONT WHEEL RIM COVER LH (N)	NOT NECESSARY	150.60	-
1	FRONT DOOR LH TRIM BOARD (N)	NOT NECESSARY	408.10	-
	LESS 25% DISCOUNT		-	-385.68
			5,636.30	1,157.02
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
1	SET FRONT DOOR TRIM BOARD CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	290.00	-
1	FRONT TYRE RIM LH (SN)	NOT NECESSARY	380.00	-
1	FRONT DOOR LH STICKER (SN)	NECESSARY	580.00	300.00
1	FRONT DOOR LH COMPANY STICKER (SN)	NECESSARY	50.00	30.00
			1,380.00	370.00
<b><u>LABOUR</u></b>				
	TO CARRY OUT ANTI-RUST TREATMENT.	NOT NECESSARY	120.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	UNDER CARRIAGE WORKS (INCLUDING REMOVAL OF SHOCK ABSORBER ,SPRING,LOWER ARM ,WHEEL HUB ,BRAKE ASSEMBLY ,WHEEL BEARING AND ALL NECESSARY).	NOT NECESSARY	380.00	-
	TRANSFER OF FRONT DOOR MECHANISM .	NOT NECESSARY	120.00	-
	TO REMOVE AND RE-STICK STICKER .	NOT NECESSARY	250.00	-
	4 WHEEL ALIGNMENT.	NOT NECESSARY	180.00	-
	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS (INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS).INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT DOOR LH STEP -UP PANEL.		800.00	300.00
	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK.		900.00	200.00
			2,750.00	500.00
	<b>GRAND TOTAL</b>		<b>9,766.30</b>	<b>2,027.02</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,600.00</b>

Report Ref No. CS/SMO23001403/Uqy3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**