



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO23001403/Uqy3q2 Date: 28/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SNF 6920H	Veh. Inspected	GBE 5152L
Policy No.	D22MTPV01013432	Coverage (\$)	0.00
Claim No.	CMTD2300564/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	09/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFHT02P800187239	Colour	SILVER
Odometer	321375 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	7 mm
L/H Front Tyre	195 R15	MICHELIN	7 mm
R/H Rear Tyre	195 R15	MICHELIN	7 mm
L/H Rear Tyre	195 R15	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/02/2023	Inspection Date	14/02/2023
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	