

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001404/UQP3Q2
Date: 03/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00026242200
Claimant Vehicle No :	XE2896H	Insured Vehicle No :	GBH7109J
Date of Loss:	03/02/2023	Nature of Claim: TP	Claim No: SNM23D200915/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE2896H	Engine No:	DC13113L016955237
Make & Model:	SCANIA P400CB8X4MHZ, 12.7 D (M)	Chassis No:	YS2P8X40005432682
Reg. Date:	26/04/2017 (Man. Year: 2016)	Odometer:	106512 km
Colour:	Multi-colour		
Engine Capacity:	12742 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D/D)
Front Left Side:	Giti 6 mm	Rear Left Side:	West Lake 6/6/6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	West Lake 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,372.00	2,172.80	5,199.20	70.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	840.00	1,540.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,752.00	3,012.80	6,739.20	69.11
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	9,752.00	2,400.00	7,352.00	75.39

INSPECTION

Date of Assignment:	09/02/2023	Inspected At:	Cheng Motor Work Company (HQ) NO.1 KAKI BUKIT AVE 6 #01-83 Singapore 417883
Date Inspected:	13/02/2023		
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2023)	
Parts:	N/A	SCANIA P400CB8X4MHZ 12.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE2896H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP N/S	Cracked	192.00 F	*192.00 FL
2	1		*NOS PLATE LAMP	Not Necessary	80.00 F	*- FL
3	1		*REAR BODY END WOODEN BEAN	Not Necessary	1,500.00 F	*- FL
4	1		*TAILGATE WOODEN (CRACKED)	Not Consistent With The Impact	2,800.00 F	*- FL
5	2		*TAILGATE HINGE	Repair	240.00 F	*- FL
6	1		*REAR BUMPER	Bent	1,500.00 FS	*1,200.00 FS
7	1		*REAR BUMPER BRACKET N/S	Bent	300.00 FS	*300.00 FS
8	1		*REAR STAND BAR	Bent	200.00 FS	*200.00 FS
9	1		*TAIL LAMP BRACKET	Bent	200.00 F	*200.00 FL
10	1		*TAILGATE DANGER-KEEP OUT STICKER	Not Necessary	150.00 F	*- FL
11	1		*60KM STICKER	Not Necessary	20.00 F	*- FL
12	1		*REAR BUMPER STICKER	Necessary	150.00 FS	*100.00 FS
13	1		*REAR NUMBER PLATE	Bent	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,372.00	2,212.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	39.20
Total Parts (\$)	7,372.00	2,172.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR KNOCKING CHASSIS FRAME ,PANEL ,WELDING ,CUTTING ,REPAIRING AND REPLACE END BEAM	New	1,500.00	500.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	800.00	320.00
3	TO CHECK WIRING	New	80.00	20.00
			Gross Labour Cost (S\$)	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >