

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LIP23001413/4943

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ~~TP WS~~ / ~~TP RES~~ / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM270165  
KT Garage

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

38252

Veh No:

SM270165

Yr Regn:

30/05/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Audi A4

c.c

1984

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

50935

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZF42K A053109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

16/11/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1/23 submit 2/5 & 7500

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : GLOBAL ADVANCE LEASING  
C/O KT GARAGE  
AutoBay@Kaki Bukit ( Entrance A).Blk 1 Kaki Bukit Ave 6, #01-04,  
Singapore 418883

Date : 28 September 2022  
Our Ref : WG/TP/2022-247

### REFERENCE PARTICULARS

Date of Accident : 08 September 2022  
Date of Inspection : 13 September 2022

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 16 September 2022

### VEHICLE PARTICULARS

Registration No : SML7016S  
Make : AUDI  
Model : A4 SEDAN 2.0 TFSI S TRONIC (NAV)  
Year : 2018

Engine No : CVK078799  
Chassis No : WAUZZZF42KA053109  
Odometer : 37924km  
Colour : Grey

### CONDITION OF VI

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	: Contential	205/60R16
Front Off Side	: Contential	205/60R16
Rear Near Side	: Contential	205/60R16
Rear off Side	: Contential	205/60R16

Thread Balance
5 mm
5 mm
5 mm
5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portions.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **SS12,050.00** nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Seven ( 07 ) working days.

Enclosed One Hundred And Four ( 104 ) photographs depicting damage to the vehicle.

Inspection conducted at : KT GARAGE  
AutoBay@Kaki Bukit ( Entrance A).Blk 1 Kaki Bukit Ave 6, #01-04, Singapore 418883

Submit \$7500  
S-Lys.

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".



VEHICLE NO : SML7016S  
MODEL : A4 SEDAN 2.0 TFSI S TRONIC (NAV)

Our Ref : WG/TP/2020-247

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

A)	SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
01	REAR BUMPER	1	DEFORMED/CRACKED	\$ 1,910.00	\$ 1,910.00
02	REAR BUMPER CENTRE PAD	1	DEFORMED/CRACKED	\$ 211.00	\$ 211.00
03	REAR BUMPER LOWER PAD	1	DEFORMED/CRACKED	\$ 215.00	\$ 215.00
04	REAR BUMPER LOWER PAD BRACKET LH	1	NECESSARY	\$ 62.00	\$ 62.00
05	REAR BUMPER LOWER PAD BRACKET RH	1	NECESSARY	\$ 62.00	\$ 62.00
06	REAR BUMPER REFLECTOR LH	1	GRAZED	\$ 32.00	\$ 32.00
07	REAR BUMPER REFLECTOR RH	1	NOT NECESSARY	\$ 32.00	\$ X NN -
08	REAR BUMPER PARKING SENSOR	4	MALFUNCTION	\$ 1,020.00	\$ 1,020.00
09	REAR BUMPER TOP BRACKET HOLDER	1	CRACKED	\$ 389.00	\$ 389.00
10	REAR BUMPER BRACKET LH	1	NECESSARY	\$ 98.00	\$ 98.00
11	REAR BUMPER BRACKET RH	1	NECESSARY	\$ 98.00	\$ 98.00
12	REAR BUMPER REINFORCEMENT	1	NOT NECESSARY	\$ 804.00	\$ NN X -
13	REAR BOOTLID	1	DENTED	\$ 2,585.00	\$ 2,585.00
14	REAR BOOTLID LOCK	1	JAMMED	\$ 189.00	\$ 189.00
15	REAR BOOTLID LOCK COVER	1	GRAZED	\$ 57.00	\$ 57.00
16	REAR BOOTLID WEATHERSTRIP	1	DEFROMED	\$ 175.00	\$ 175.00
17	TAILLAMP LH	1	CRACKED	\$ 955.00	\$ NN X 955.00
18	TAILLAMP RH	1	NOT NECESSARY	\$ 955.00	\$ NN X -
19	TAILLAMP SIDE COVER LH	1	CRACKED	\$ 45.00	\$ NN X 45.00
20	TAILLAMP SIDE COVER RH	1	NOT NECESSARY	\$ 45.00	\$ NN X -
21	END PANEL OUTER	1	DENTED	\$ 1,451.00	\$ R X 1,451.00 X
22	END PANEL INNER	1	REPAIR	\$ 1,599.00	\$ R X 1,599.00 X
23	END PANEL TOP GARNISH	1	NOT NECESSARY	\$ 235.00	\$ NN X -
24	KEYLESS ANTENA	1	MALFUNCTION	\$ 119.00	\$ 119.00
25	EXHAUST CHROME CUTTER - LH	1	GRAZED	\$ 198.00	\$ 198.00
26	EXHAUST CHROME CUTTER - RH	1	GRAZED	\$ 198.00	\$ 198.00
				\$ 13,739.00	\$ 11,668.00
				Less 10%	\$ 1,373.90
				\$ 12,365.10	\$ 10,501.20
B)	<u>S/NETT ITEM</u>				
27	REAR BUMPER CLIP	1 SET	NECESSARY NN	\$ 40.00	\$ 30.00 X
28	TAILLAMP SIIDE COVER CLIP	1 SET	NECESSARY NN	\$ 40.00	\$ 30.00 X
29	JOINT SEALANT	1	NECESSARY NN	\$ 150.00	\$ 130.00 X
				\$ 230.00	\$ 190.00

Parts Total :

\$ 12,595.10 \$ 10,691.20

C) LABOUR CHARGES & MISC

30	CHECK REAR LIGHTNING AND WIRING SYSTEM	\$	100.00	\$	20	90.00
31	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	\$	200.00	\$	80	180.00
32	REMOVE AND RENEW REAR REVERSE SENSOR	\$	150.00	\$	50	120.00
33	REMOVE AND STRIAGHTEN REAR EXHAUST	\$	150.00	\$	12	130.00
34	DIAGNOSIS CHECK AND CLEAR FAULT CODE	\$	600.00	\$	12X	500.00
35	TRNSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	\$	200.00	\$	80	180.00
36	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	\$	1,500.00	\$	600	1,400.00
37	SPRAY PAINTING ON AFFECTED AREAS	\$	2,000.00	\$	800	1,800.00
Labour Total :		\$	4,900.00	\$		4,400.00

Total Parts and Laboure :

\$	17,495.10	\$	15,091.20
----	-----------	----	-----------

FINAL LUMP SUM ADJUSTMENT

\$ 12,050.00

**POINT OF IMPACT**

The impact was confined to the rear portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

**ADJUSTMENT/RECOMMENDATIONS**

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

**CONCLUSION**

The repairer has agreed to undertake repair the vehicle at a lump sum basis of **SS\$12,050.00 nett** corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES



Winson Goh  
Automotive Appraiser

2596  
2618  
1416  
7532