

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI23001414/KVP3Q2**Date:** 12/06/2023**REFERENCE**

Insured/Claimant: GTS ENGINEERING PTE LTD Policy No: DMCVSNW00107052202

Date of Loss: 01/02/2023

Nature of Claim: OD

Claim No: SNM23D200908/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBE1520J</b>	Engine No:	ZD30001401N
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0857565
Reg. Date:	19/09/2015 (Man. Year: 2015)	Odometer:	234856 km
Colour:	Gold		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	S\$31,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	165 R12X8 (D)
Front Left Side:	Toyo 4 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Yokohama 7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,895.00	4,516.00	1,379.00	23.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,716.00	2,632.09	83.91	3.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,611.00</b>	<b>7,148.09</b>	<b>1,462.91</b>	<b>16.99</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,100.00</b>		
<b>- Excess (S\$)</b>	0.00	500.00	-500.00	
<b>(S\$)</b>	8,611.00	6,600.00	2,011.00	23.35
<b>+ GST 8.00/8.00% (S\$)</b>	688.88	528.00	160.88	23.35
<b>Nett Amount (S\$)</b>	<b>9,299.88</b>	<b>7,128.00</b>	<b>2,171.88</b>	<b>23.35</b>

**INSPECTION**

Date of Assignment:	08/02/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	09/02/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Jun 2023)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE1520J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		<b>*PARTS</b>		5,500.00 F	*5,250.00 FL	
<b>Supplementary #1</b>							
2	1		<b>*CRANKSHAFT PULLEY</b>	Cracked	300.00 F	*300.00 FL	
3	1		<b>*L/F SHOCK ABSORBER</b>	Bent	95.00 F	*95.00 FL	
					<b>Sub Total (S\$)</b>	<b>5,895.00</b>	<b>5,645.00</b>
					<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	1,129.00
					<b>Total Parts (S\$)</b>	<b>5,895.00</b>	<b>4,516.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	1,236.00	1,382.09
<b>Supplementary #1</b>				
<b>Labour Items</b>				
2	TO STRAIGHTEN , KNOCK, REPAIR AND REALIGN RH MAIN CHASSIS	New	800.00	800.00
3	REMOVE AND REFIT ENGINE, GEARBOX(TO REPAIR MAIN CHASSIS)	New	280.00	250.00
4	REMOVE AND REFIT CRANK SHAFT PULLEY AND RESET ENGINE	New	200.00	0.00
5	REMOVE AND REFIT REAR CANOPY, REAR TRUCK.	New	200.00	200.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,716.00</b>
				<b>2,632.09</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >