

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 09 Feb 2023

Preliminary Advice

Vehicle No	: GBE1520J	Accident Date	: 01/02/2023
Make	: NISSAN CABSTAR	Policy No.	: DMCVSNW00107052202
Assignment Date	: 08/02/2023	Excess	: S\$500.00
Date of Inspection	: 9/2/2023	Est. Duration of Repair	: 4
Inspection At	: CHENG HOE MOTOR PL		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,736.00
Revised Amount	:S\$	4,786.00
Check Items (Estimated)	:S\$	1,770.00
Total	:S\$	6,556.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	31,000.00
COE / PARF Rebate	:S\$	11,664.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,336.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost

At the time of inspection, all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately Tyre Condition (Front) :4 mm ,(Rear) : 7mm