

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001416/UQP3M4**Date:** 13/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00002262301

Claimant Vehicle No : PC9187E **Insured Vehicle No :** GBJ1700E

Date of Loss: 07/02/2023 Nature of Claim: TP Claim No: SNM23D201035/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC9187E**

Make & Model: TOYOTA HIACE, 2.8 D COMMUTER GL (A) Engine No: 1GD8520249

Reg. Date: 25/03/2020 (Man. Year: 2019) Chassis No: GDH2232002870

Colour: White Odometer: 58818 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,425.31	3,787.85	2,637.46	41.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,470.00	1,710.00	53.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,605.31	5,257.85	4,347.46	45.26
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	9,605.31	4,200.00	5,405.31	56.27
+ GST 8.00/8.00% (S\$)	768.42	336.00	432.42	56.27
Nett Amount (S\$)	10,373.73	4,536.00	5,837.73	56.27

INSPECTION

Date of Assignment: 07/03/2023

Date Inspected: 20/02/2023 Inspected At:

KT GARAGE PTE LTD
BLK 1 KAKI BUKIT AVE 6 #01-04
AUTO BAY@KAKI BUKIT ENTRANCE A
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC9187E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	475.00 FL	*475.00 FL
2	1		*SET REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
3	3		*REAR BUMPER LOWER BRACKET	Bent	90.00 FL	*90.00 FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	130.00 FL	*- FL
5	1		*TAILGATE	Badly Dented	2,450.00 FL	*2,245.00 FL
6	1		*TAILGATE LOGO	Necessary	80.00 FL	*80.00 FL
7	1		*TAILGATE HIACE EMBLEM	Necessary	78.00 FL	*78.00 FL
8	1		*TAILGATE INNER TRIMBOARD	Deformed/Torn	608.50 FL	*608.50 FL
9	1		*TAILGATE LOCK	Dented/Jammed	332.70 FL	*332.70 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	280.60 FL	*280.60 FL
11	1		*TAILGATE OUTER HANDLE	Not Necessary	180.70 FL	*- FL
12	1		*END PANEL - OUTER	Dented	450.00 FL	*450.00 FL
13	1		*END PANEL - INNER	Repair	1,090.50 FL	*- FL
14	2		*REAR CORNER PANEL	Repair	201.10 FL	*- FL
15	2		*REAR NUMBER PLATE LAMP	Not Necessary	198.80 FL	*- FL
16	1		*TAILGATE WINDSCREEN SEALANT	Necessary	28.00 FS	*28.00 FS
17	2		*TAILGATE WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
18	1		*70 KM/HR STICKER	Necessary	28.00 FS	*10.00 FS
19	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
20	1		*SET REAR PARKING SENSOR	Shorted	252.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,093.90	4,957.80
- List Item Discount on L Items 10.00/25.00% (S\$)	668.59	1,169.95
Total Parts (S\$)	6,425.31	3,787.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, KNOCK AND STRAIGHTEN DAMAGED PANEL AND RE-ALIGN THE SAME	New	1,650.00	600.00
2	TO REMOVE REAR WINDSCREEN	New	150.00	120.00
3	TO REMOVE UPHOLSTERY	New	120.00	80.00
4	TO SPRAY PAINT THE AFFECTED AREAS	New	900.00	500.00
5	TO RUST PROOF ALL AFFECTED AREAS	New	80.00	50.00
6	TO TRANSFER TAILGATE	New	100.00	60.00
7	TO CHECK ALL NECESSARY LIGHTING	New	80.00	20.00
8	INSTALL PARKING SENSOR	New	100.00	40.00
Gross Labour Cost (\$\$)			3,180.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >