

ASS. REC. BY:

REF:

TU / 2300147/Kp

Kenneth

GPB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / GIA & Est not ready

2 / 2022 11/11 @ 2000 Cnhr

Veh No:

SKP 0265 Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Hyundai Elantra c.c 1591

Colour

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

364480 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DH 41CM EU 208248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Finanz

Front

Rear

R/Bal.

4 mm

R/Bal.

3

mm

L/Bal.

4 mm

L/Bal.

3

mm

D.O.A.

8/2/23

D.O.I.

9/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation

S - RS. SI

F. P. M.

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI ELANTRA

Engine/Chassis No.: KMHDH41CMEU208248

Date of accident: 08.02.23


Damaged area: N/S Front

Date: 09/02/2023

Claim Type: TP

VRN: SKP626E

*Not Authorized
L1 Day & 2000p.
Resurvey After Paint
3 days*



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper <i>485 mgcm</i>	1	\$ 814.00	\$ 814.00
2	Front bumper side retainer <i>nl s di</i>	2	\$ 54.00	\$ 108.00
3	Front bumper tow cover <i>sn</i>	1	\$ 66.00	\$ 66.00
4	Front bumper foglamp cover n/s <i>sn</i>	1	\$ 193.00	\$ 193.00
5	Front bumper lower cowlings <i>sn</i>	1	\$ 243.00	\$ 243.00
6	Headlamp n/s <i>mgcm</i>	1	\$ 1,408.00	\$ 1,408.00
7	Headlamp lower bracket n/s <i>cm</i>	1	\$ 61.00	\$ 61.00
8	Headlamp support n/s <i>sn</i>	1	\$ 316.00	\$ 316.00
9	Bonnet <i>sn</i>	1	\$ 973.00	\$ 973.00
10	Bonnet hinge <i>R</i>	2	\$ 77.00	\$ 154.00
11	Bonnet seal <i>sn</i>	1	\$ 34.00	\$ 34.00
12	Front bumper fog lamp n/s <i>289 mgcm</i>	1	\$ 326.00	\$ 326.00
Subtotal				\$ 4,696.00
List discount				20.00%
Total				\$ 3,756.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips <i>sn</i>	10	\$ 4.50	\$ 45.00
2	Bonnet insulator clips <i>sn</i>	10	\$ 4.50	\$ 45.00
3	Front fender inner cowlings clips n/s <i>sn</i>	8	\$ 4.50	\$ 36.00
4	Sundries <i>sn</i>	1	\$ 50.00	\$ 50.00
Total				\$ 176.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

300p