

ASS. REC. BY:

REF:

TII / 2300147/Kp
GRB

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 0265 Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra c.c. 1591

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

364480

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH DH 41 CM EU 208248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Finanz

Front

Rear

R/Bal.

4 mm

R/Bal.

3 mm

L/Bal.

4 mm

L/Bal.

3 mm

D.O.A.

8/2/23

D.O.I.

9/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

GIA & Est not ready

24/2 11pm @ 2000 Car

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI ELANTRA
 Engine/Chassis No.: KMMDH41CMEU208248
 Date of accident: 08.02.23
 Damaged area: N/S Front

Date: 09/02/2023
 Claim Type: TP
 VRN: SKP626E

Not Authorized
1/1 Sep & 2000p
Resurvey After Paint
3 days



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper <i>485 mgcm</i>	1	\$ 814.00	\$ 814.00
2	Front bumper side retainer <i>n/s dis</i>	2	\$ 54.00	\$ 108.00
3	Front bumper tow cover <i>sn</i>	1	\$ 66.00	\$ 66.00
4	Front bumper foglamp cover n/s <i>sn</i>	1	\$ 193.00	\$ 193.00
5	Front bumper lower cowlng <i>sn</i>	1	\$ 243.00	\$ 243.00
6	Headlamp n/s <i>mgcm</i>	1	\$ 1,408.00	\$ 1,408.00
7	Headlamp lower bracket n/s <i>cm</i>	1	\$ 61.00	\$ 61.00
8	Headlamp support n/s <i>sn</i>	1	\$ 316.00	\$ 316.00
9	Bonnet <i>R</i>	1	\$ 973.00	\$ 973.00
10	Bonnet hinge <i>R</i>	2	\$ 77.00	\$ 154.00
11	Bonnet seal <i>sn</i>	1	\$ 34.00	\$ 34.00
12	Front bumper fog lamp n/s <i>289 mgcm</i>	1	\$ 326.00	\$ 326.00
Subtotal				\$ 4,696.00
List discount				20.00%
Total				\$ 3,756.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips <i>mn</i>	10	\$ 4.50	\$ 45.00
2	Bonnet insulator clips <i>mn</i>	10	\$ 4.50	\$ 45.00
3	Front fender inner cowlng clips n/s <i>mn</i>	8	\$ 4.50	\$ 36.00
4	Sundries <i>mn</i>	1	\$ 50.00	\$ 50.00
Total				\$ 176.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

300

2	To disconnect components functions incl
3	Supply spray respray affect
4	To rust proof

200
4000
X