



Your Ref: 2022 - 77

Date: 15th Feb 2023

Our Ref: CS1/SCD23001418/Dqy3e2

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBL 5421Z
INSURED VEHICLE: QX 2490C
ACCIDENT DATE: 05/08/2022**

We thank you for your instruction on 09/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBL 5421Z from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement and Police Report of Vehicles FBL 5421Z.
- c) Final Repair Bill of FBL 5421Z from M/s Kim Keat Motor Co.
- d) Colour damaged vehicle photographs of FBL 5421Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBL 5421Z
Make & Model	: Piaggio Vespa Sprint Sport 150 ABS
Chassis Number	: ZAPM8140100001314
Year of Registration	: 2016
Engine Capacity	: 155 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 5421Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP ASSY	CRACKED	185.00	185.00
1	FRONT HEADLAMP RIM	CRACKED	48.00	48.00
2	SET FRONT MIRROR L/R	CRACKED	165.00	165.00
2	SET HANDLE GRIP L/R	CUT	92.00	92.00
1	BRAKE LEVER LH	CRACKED	78.00	78.00
1	FRONT HANDLE BAR	BENT	188.00	188.00
1	FRONT HANDLE BAR COWLING ASSY	CRACKED	280.00	280.00
1	FRONT SIDE SIGNAL L/R	TO REPAIR SEE LABOUR	182.00	-
1	FRONT FENDER	CRACKED	286.00	225.00
1	FRONT FORK WITH SUSPENSION ARM ASSY	BENT	1,086.00	980.00
1	FRONT WHEEL	TO REPAIR SEE LABOUR	345.00	-
1	SET FRONT WHEEL BEARING	JAMMED	85.00	85.00
1	SET BODY COVER	CRACKED	1,550.00	1,200.00
1	MAIN PARKING STAND	BENT	215.00	215.00
1	REAR INTAKE CONNECTION BELT COVER	CRACKED	78.00	78.00
1	REAR SIDE BELT COVER CASE	CUT	615.00	615.00
1	REAR WHEEL	TO REPAIR SEE LABOUR	345.00	-
1	REAR WHEEL BEARING	NOT NECESSARY	85.00	-
	LESS 5% DISCOUNT		-295.40	-
	LESS 10% DISCOUNT		-	-443.40
			5,612.60	3,990.60
<u>SPECIAL NETT ITEMS</u>				
2	FRONT NUMBER PLATE STICKER (SN)	NECESSARY	50.00	40.00
1	SET FRONT LEG SHIELD PANEL PROTECTOR STRIPE (SN)	CRACKED	120.00	100.00
1	SET BODY PROTECTOR GUIDE BAR (SN)	BENT	450.00	400.00
1	SET FOOT STEP STRIPE PAD L/R (SN)	CUT	220.00	180.00
1	REAR STORAGE BOX (SN)	BENT	300.00	300.00

Report Ref No. CS1/SCD23001418/Dqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR STORAGE BOX BRACKET (SN)	NOT NECESSARY	120.00	-
			1,260.00	1,020.00
	LABOUR			
	TO PROVIDE TOWING CHARGE.		50.00	50.00
	WHEEL ALIGNMENT.		100.00	80.00
	TO CHECK, ALIGN AND BALANCE BODY MAIN FRAME.		250.00	150.00
	SPRAY PAINTING.		500.00	300.00
	LABOUR FOR REPAIR AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT SIDE SIGNAL L/R, FRONT WHEEL AND REAR WHEEL.		1,200.00	400.00
			2,100.00	980.00
GRAND TOTAL			8,972.60	5,990.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS1/SCD23001418/Dqy3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.