



# PRIORITY SERVICES

## INSURANCE LOSS ADJUSTERS AND MOTOR APPRAISERS

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779  
Tel: 6293 4822 Fax: 6296 3283

### VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block, MND Complex  
Singapore 069110

**Our File No:** OD-0129/11/22  
**Date:** 27/12/2022

#### REFERENCE

Insured/Claimant: CHIN LIAN WAAH REBECCA Policy No: DMPPHQ22-005728  
Date of Loss: 10/11/2022 Nature of Claim: OD Claim No: DM22HO01955

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR5892Y  
Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CP5351  
Reg. Date: 21/08/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006888  
Colour: Metallic Red Odometer: 129015 km  
Engine Capacity: 1590 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

#### CONDITION OF TYRES

Front Tyre Size: 205/60/16 Rear Tyre Size: 205/60/16  
Front Left Side: Yokohama 3 mm Rear Left Side: Goodyear 3 mm  
Front Right Side: Yokohama 3 mm Rear Right Side: Goodyear 3 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 10,662.30        | 5,884.50        | 4,777.80        | 44.81        |
| Miscellaneous Items                      | 60.00            | 35.00           | 25.00           | 41.67        |
| Labour                                   | 4,580.00         | 1,950.00        | 2,630.00        | 57.42        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>15,302.30</b> | <b>7,869.50</b> | <b>7,432.80</b> | <b>48.57</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>6,250.00</b> |                 |              |
| <b>- Excess (S\$)</b>                    | 500.00           | 500.00          | 0.00            | 0.00         |
| <b>(S\$)</b>                             | 14,802.30        | 5,750.00        | 9,052.30        | 61.15        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,036.17         | 402.50          | 633.67          | 61.16        |
| <b>Nett Amount (S\$)</b>                 | <b>15,838.47</b> | <b>6,152.50</b> | <b>9,685.97</b> | <b>61.15</b> |

#### INSPECTION

Date of Assignment: 23/11/2022 Present Location: Elite Automotive Pte Ltd (HQ)  
Elite Automotive Pte Ltd (HQ)  
Date Inspected: 23/11/2022 Inspected At: 280 Woodlands Industrial Park E5, #01-17,  
Harvest@Woodlands  
Singapore 757322  
Estimated Period of Repair: 7.0 days

**LOU BENEFIT -7 DAYS X \$50/- = \$350/-**

**Adjuster:** JEFFREY ONG  
Surveyor

**Manager:** Sharon Kho  
Administrator

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                                 |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 27 Dec 2022)                                   |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                               |
| <b>Print Code:</b>   | <b>Priority Services/SLR5892Y/27/12/2022 15:47</b>                                                                                                                           |                                                                                 |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                 |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                 |

### Recommended Parts

| No.                     | Qty | Part No. | Particulars                                | Condition                    | Repairer's | Amount      |
|-------------------------|-----|----------|--------------------------------------------|------------------------------|------------|-------------|
| 1                       | 1   |          | *BONNET                                    | dented                       | 520.00 F   | *430.00 F   |
| 2                       | 1   |          | *BONNET LOCK                               | bent                         | 50.00 F    | *50.00 F    |
| 3                       | 1   |          | *BONNET INSULATION                         | deformed                     | 80.00 F    | *60.00 F    |
| 4                       | 15  |          | *BONNET INSULATION CLIPS                   | necessary                    | 45.00 F    | *30.00 FS   |
| 5                       | 2   |          | *BONNET HINGES (LH & RH)                   | bent                         | 100.00 F   | *80.00 F    |
| 6                       | 1   |          | *BONNET STAND                              | refit                        | 30.00 F    | Refit       |
| 7                       | 1   |          | *BONNET STAND CLIP                         | not necessary                | 3.00 F     | See Remarks |
| 8                       | 1   |          | *BONNET RUBBERSTRIP                        | torn                         | 60.00 F    | *20.00 F    |
| 9                       | 1   |          | *FRONT GRILLE                              | cracked                      | 350.00 F   | *160.00 F   |
| 10                      | 1   |          | *HEADLAMP (LH & RH)                        | LH broken                    | 1,000.00 F | *440.00 F   |
| 11                      | 1   |          | *HEADLAMP LOWER BRACKET (LH & RH)          | LH cracked                   | 160.00 F   | *20.00 F    |
| 12                      | 1   |          | *FRONT BUMPER                              | dented/cracked               | 580.00 F   | *470.00 F   |
| 13                      | 10  |          | *FRONT BUMPER CLIPS                        | necessary                    | 30.00 F    | *30.00 FS   |
| 14                      | 1   |          | *FRONT BUMPER RETAINER (LH & RH)           | LH cracked                   | 40.00 F    | *20.00 F    |
| 15                      | 1   |          | *FRONT BUMPER REINFORCEMENT                | bent                         | 290.00 F   | *220.00 F   |
| 16                      | 1   |          | *FRONT BUMPER LOWER GRILLE                 | cracked                      | 70.00 F    | *45.00 F    |
| 17                      | 1   |          | *FRONT BUMPER LOWER GRILLE CHROME MOULDING | cracked                      | 280.00 F   | *130.00 F   |
| 18                      | 2   |          | *FOG LAMP (LH & RH)                        | refit                        | 500.00 F   | Refit       |
| 19                      | 1   |          | *FOG LAMP COVER (LH & RH)                  | LH grazed                    | 100.00 F   | *50.00 F    |
| 20                      | 1   |          | *FRONT FENDER (LH & RH)                    | LH buckled/dented, RH repair | 760.00 F   | *310.00 F   |
| 21                      | 1   |          | *FRONT SPLASH SHIELD (LH & RH)             | LH torn                      | 210.00 F   | *75.00 F    |
| 22                      | 10  |          | *FRONT SPLASH SHIELD CLIPS                 | necessary                    | 60.00 F    | *30.00 FS   |
| 23                      | 1   |          | *WIPER GARNISH                             | refit                        | 100.00 F   | Refit       |
| 24                      | 1   |          | *A/C CONDENSER                             | bent                         | 630.00 F   | *630.00 F   |
| 25                      | 1   |          | *RADIATOR                                  | bent                         | 600.00 F   | *600.00 F   |
| 26                      | 1   |          | *FAN BLADE                                 | refit                        | 60.00 F    | Refit       |
| 27                      | 1   |          | *FAN MOTOR                                 | refit                        | 280.00 F   | Refit       |
| 28                      | 1   |          | *FAN COWLING                               | refit                        | 230.00 F   | Refit       |
| 29                      | 1   |          | *A/C LIQUID PIPE                           | refit                        | 120.00 F   | Refit       |
| 30                      | 1   |          | *A/C DISCHARGE PIPE                        | refit                        | 190.00 F   | Refit       |
| 31                      | 1   |          | *A/C SUCTION PIPE                          | refit                        | 250.00 F   | Refit       |
| 32                      | 1   |          | *SUPPORT PANEL                             | dented                       | 600.00 F   | *460.00 F   |
| 33                      | 1   |          | *SUPPORT PANEL UPPER GARNISH               | deformed                     | 55.00 F    | *30.00 F    |
| 34                      | 1   |          | *SUPPORT PANEL UPPER GARNISH CLIPS         | necessary                    | 45.00 F    | *25.00 FS   |
| 35                      | 1   |          | *TOWING CAP                                | refit                        | 30.00 F    | Refit       |
| <b>Supplementary #1</b> |     |          |                                            |                              |            |             |
| 36                      | 1   |          | *SUPPORT TOP PANEL                         | dented                       | 220.00 F   | *220.00 F   |
| 37                      | 1   |          | *HEADLAMP PANEL (LH & RH)                  | LH dented                    | 160.00 F   | *60.00 F    |
| 38                      | 1   |          | *FRONT BUMPER UNDER COVER                  | torn                         | 290.00 F   | *150.00 F   |
| 39                      | 1   |          | *RHS DAY LIGHT                             | grazed                       | 380.00 F   | *380.00 F   |
| 40                      | 1   |          | *FRONT BUMPER LOWER GRILLE COVER (LHS)     | dislodged/missing            | 15.00 F    | *15.00 F    |
| 41                      | 1   |          | *FRONT BUMPER SUPPORT                      | bent                         | 120.00 F   | *120.00 F   |

F=Franchise part. S=SpcNett.

**Priority Services/SLR5892Y/27/12/2022 15:47.** Not valid without Reference section.

| No. | Qty | Part No. | Particulars | Condition | Repairer's                                      | Amount           |
|-----|-----|----------|-------------|-----------|-------------------------------------------------|------------------|
|     |     |          |             |           | <b>Sub Total (S\$)</b>                          | <b>9,693.00</b>  |
|     |     |          |             |           | <b>+ Margin on L,N Items 10.00/10.00% (S\$)</b> | <b>969.30</b>    |
|     |     |          |             |           | <b>Total Parts (S\$)</b>                        | <b>10,662.30</b> |

**5,360.00**  
**524.50**

**5,884.50**

**Priority Services/SLR5892Y/27/12/2022 15:47. Not valid without Reference section.**

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                            | Repairer's   | Amount       |
|----------------------------|-----|----------------------------------------|--------------|--------------|
| <b>Miscellaneous Items</b> |     |                                        |              |              |
| 1                          | 1   | FRONT NUMBER PLATE WITH HOLDER<br>bent | 60.00        | 35.00        |
| <b>Sub Total (\$\$)</b>    |     |                                        | <b>60.00</b> | <b>35.00</b> |

## Recommended Labour

| No                              | Particulars                                                                                                                                         | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                     |          |                 |                 |
| 1                               | LABOUR CHARGES TO REMOVE DAMAGED PARTS & FITTINGS TO<br>ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO<br>REPLACE DAMAGED PARTS AS LISTED ABOVE. | New      | 2,000.00        | 800.00          |
| 2                               | TO SPRAY PAINTING ON: BONNET, SUPPORT PANEL, FRONT<br>BUMPER, A PILLAR (LH & RH), FRONT BOTH FENDER, FRONT BOTH<br>DOOR.                            | New      | 1,800.00        | 1,000.00        |
| 3                               | TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO<br>ENABLE REPAIRS; TO VACUUM & CHARGE UP GAS                                                 | New      | 150.00          | 120.00          |
| 4                               | TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIRS,<br>INCLUDING PRESSURIZE COOLING SYSTEM.<br>- included in item 3                             | New      | 150.00          | 0.00            |
| 5                               | TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE<br>FOCUS HEADLIGHTS.                                                                       | New      | 200.00          | 30.00           |
| 6                               | CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT<br>REPAIRS.                                                                                      | New      | 280.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                     |          | <b>4,580.00</b> | <b>1,950.00</b> |

Priority Services/SLR5892Y/27/12/2022 15:47. Not valid without Reference section.

< END OF ESTIMATES >