

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Date: 05th Jun 2023 Your Ref: ACS/105/009/2022/115

Our Ref: CS1/SPF23001421/Tny3e2

## M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section (Spore Police Force) Police Logistics Base (PLB) 1 Hemmant Road Singapore 438675 (The Motor Claims Department)

Attn: Hafizul Farhan

Dear Sir / Madam,

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLR 5892Y INSURED VEHICLE: QX 1934X ACCIDENT DATE: 10/11/2022**

We thank you for your instruction on 08/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLR 5892Y from M/s Priority Services.
- b) Singapore Accident Statement of Vehicles SLR 5892Y.
- c) Colour damaged vehicle photographs of SLR 5892Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLR 5892Y

Make & Model : Mitsubishi Lancer EX 1.6 AT Led Tail Lamp

: 2017

Year of Registration Chassis Number : JMYSRCY1AGU006888

**Engine Capacity** : 1590 cc



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

2.	Our finding is that the repair cost of \$6,250.00 (before GST) quoted by M/s Priority Services is
	fair & reasonable.

3. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.

Vehicle Inspected By:

MOHAMAD TAUFIKH M.MATAI, AMSAE-A Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.