



PRIORITY SERVICES

INSURANCE LOSS ADJUSTERS AND MOTOR APPRAISERS

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel: 6293 4822 Fax: 6296 3283

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: OD-0129/11/22
Date: 27/12/2022

REFERENCE

Insured/Claimant: CHIN LIAN WAAH REBECCA Policy No: DMPPHQ22-005728
Date of Loss: 10/11/2022 Nature of Claim: OD Claim No: DM22HO01955

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR5892Y
Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CP5351
Reg. Date: 21/08/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006888
Colour: Metallic Red Odometer: 129015 km
Engine Capacity: 1590 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 205/60/16 Rear Tyre Size: 205/60/16
Front Left Side: Yokohama 3 mm Rear Left Side: Goodyear 3 mm
Front Right Side: Yokohama 3 mm Rear Right Side: Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,662.30	5,884.50	4,777.80	44.81
Miscellaneous Items	60.00	35.00	25.00	41.67
Labour	4,580.00	1,950.00	2,630.00	57.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,302.30	7,869.50	7,432.80	48.57
Approved Total (Overridden) (S\$)		6,250.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,802.30	5,750.00	9,052.30	61.15
+ GST 7.00/7.00% (S\$)	1,036.17	402.50	633.67	61.16
Nett Amount (S\$)	15,838.47	6,152.50	9,685.97	61.15

INSPECTION

Date of Assignment: 23/11/2022 Present Location: Elite Automotive Pte Ltd (HQ)
Date Inspected: 23/11/2022 Inspected At: Elite Automotive Pte Ltd (HQ)
280 Woodlands Industrial Park E5, #01-17,
Harvest@Woodlands
Singapore 757322
Estimated Period of Repair: 7.0 days

LOU BENEFIT -7 DAYS X \$50/- = \$350/-

Adjuster: JEFFREY ONG
Surveyor

Manager: Sharon Kho
Administrator

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)
Parts:	143	MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Priority Services/SLR5892Y/27/12/2022 15:47	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	dented	520.00 F	*430.00 F
2	1		*BONNET LOCK	bent	50.00 F	*50.00 F
3	1		*BONNET INSULATION	deformed	80.00 F	*60.00 F
4	15		*BONNET INSULATION CLIPS	necessary	45.00 F	*30.00 FS
5	2		*BONNET HINGES (LH & RH)	bent	100.00 F	*80.00 F
6	1		*BONNET STAND	refit	30.00 F	Refit
7	1		*BONNET STAND CLIP	not necessary	3.00 F	See Remarks
8	1		*BONNET RUBBERSTRIP	torn	60.00 F	*20.00 F
9	1		*FRONT GRILLE	cracked	350.00 F	*160.00 F
10	1		*HEADLAMP (LH & RH)	LH broken	1,000.00 F	*440.00 F
11	1		*HEADLAMP LOWER BRACKET (LH & RH)	LH cracked	160.00 F	*20.00 F
12	1		*FRONT BUMPER	dented/cracked	580.00 F	*470.00 F
13	10		*FRONT BUMPER CLIPS	necessary	30.00 F	*30.00 FS
14	1		*FRONT BUMPER RETAINER (LH & RH)	LH cracked	40.00 F	*20.00 F
15	1		*FRONT BUMPER REINFORCEMENT	bent	290.00 F	*220.00 F
16	1		*FRONT BUMPER LOWER GRILLE	cracked	70.00 F	*45.00 F
17	1		*FRONT BUMPER LOWER GRILLE CHROME MOULDING	cracked	280.00 F	*130.00 F
18	2		*FOG LAMP (LH & RH)	refit	500.00 F	Refit
19	1		*FOG LAMP COVER (LH & RH)	LH grazed	100.00 F	*50.00 F
20	1		*FRONT FENDER (LH & RH)	LH buckled/dented, RH repair	760.00 F	*310.00 F
21	1		*FRONT SPLASH SHIELD (LH & RH)	LH torn	210.00 F	*75.00 F
22	10		*FRONT SPLASH SHIELD CLIPS	necessary	60.00 F	*30.00 FS
23	1		*WIPER GARNISH	refit	100.00 F	Refit
24	1		*A/C CONDENSER	bent	630.00 F	*630.00 F
25	1		*RADIATOR	bent	600.00 F	*600.00 F
26	1		*FAN BLADE	refit	60.00 F	Refit
27	1		*FAN MOTOR	refit	280.00 F	Refit
28	1		*FAN COWLING	refit	230.00 F	Refit
29	1		*A/C LIQUID PIPE	refit	120.00 F	Refit
30	1		*A/C DISCHARGE PIPE	refit	190.00 F	Refit
31	1		*A/C SUCTION PIPE	refit	250.00 F	Refit
32	1		*SUPPORT PANEL	dented	600.00 F	*460.00 F
33	1		*SUPPORT PANEL UPPER GARNISH	deformed	55.00 F	*30.00 F
34	1		*SUPPORT PANEL UPPER GARNISH CLIPS	necessary	45.00 F	*25.00 FS
35	1		*TOWING CAP	refit	30.00 F	Refit
Supplementary #1						
36	1		*SUPPORT TOP PANEL	dented	220.00 F	*220.00 F
37	1		*HEADLAMP PANEL (LH & RH)	LH dented	160.00 F	*60.00 F
38	1		*FRONT BUMPER UNDER COVER	torn	290.00 F	*150.00 F
39	1		*RHS DAY LIGHT	grazed	380.00 F	*380.00 F
40	1		*FRONT BUMPER LOWER GRILLE COVER (LHS)	dislodged/missing	15.00 F	*15.00 F
41	1		*FRONT BUMPER SUPPORT	bent	120.00 F	*120.00 F

F=Franchise part. S=SpcNett.

Priority Services/SLR5892Y/27/12/2022 15:47. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (\$)	9,693.00
					+ Margin on L,N Items 10.00/10.00% (\$)	524.50
					Total Parts (\$)	10,662.30

Priority Services/SLR5892Y/27/12/2022 15:47. Not valid without Reference section.
--

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE WITH HOLDER bent	60.00	35.00
Sub Total (\$\$)			60.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE DAMAGED PARTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	New	2,000.00	800.00
2	TO SPRAY PAINTING ON: BONNET, SUPPORT PANEL, FRONT BUMPER, A PILLAR (LH & RH), FRONT BOTH FENDER, FRONT BOTH DOOR.	New	1,800.00	1,000.00
3	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS; TO VACUUM & CHARGE UP GAS	New	150.00	120.00
4	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIRS, INCLUDING PRESSURIZE COOLING SYSTEM. - included in item 3	New	150.00	0.00
5	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	New	200.00	30.00
6	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	New	280.00	0.00
Gross Labour Cost (\$\$)			4,580.00	1,950.00

Priority Services/SLR5892Y/27/12/2022 15:47. Not valid without Reference section.

< END OF ESTIMATES >