



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 7238U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT N/S HEADLAMP	NOT NECESSARY	1,955.00	-
1	FRONT BUMPER	DAMAGED	1,887.00	1,201.30
1	SET FRONT BUMPER CLIP	NECESSARY	65.00	65.00
1	FRONT BUMPER N/S SIDE RETAINER	NECESSARY	75.50	75.50
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	1,470.00	-
1	FRONT N/S FENDER	DAMAGED	1,085.00	891.00
1	FRONT N/S FENDER INNER SHIELD	DAMAGED	185.00	185.00
	LESS 5% DISCOUNT		-336.13	-
	LESS 10% DISCOUNT		-	-241.78
			6,386.37	2,176.02
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER LOWER SPOILER (SN)	NOT NECESSARY	750.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	55.00	30.00
1	FRONT N/S TYRE (SN)	NOT NECESSARY	500.00	-
1	FRONT N/S WHEEL RIM (SN)	NOT NECESSARY	1,250.00	-
			2,555.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING, LIGHTING AND RESETTNG HEADLAMPS FOCUSING.		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		100.00	30.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR.		1,080.00	500.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	660.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.		300.00	200.00
			2,710.00	1,420.00
GRAND TOTAL			11,651.37	3,626.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS3/LPC23000198/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.