

CL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Anand Kumar Ram Kumar @Muhammad Ridwan
Ashsiddiq Bin Abdullah
C/o: FDK Automobile & Leasing Services Pte Ltd
39 Woodlands Close
#05-12 Mega @ Woodlands Singapore 737856

Date : 16 January 2023
Our ref : FDK/01/2301/TP

Accident Date : 1 January 2023
Inspection Date : 10 January 2023
Repairer Name : FDK Automobile & Leasing Services Pte Ltd
39 Woodlands Close
#05-12 Mega @ Woodlands Singapore 737856

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SKB 7238 U
Make / Model : Mercedes Benz C180K
Chassis No : WDD2040452A426247
Engine No : 27191031330760

Year / Capacity : 2010 / 1597 cc
Colour : Black
Mileage : 154589

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside :	Falken	225/45 R18	5 mm	Sport
Front Offside :	Falken	225/45 R18	5 mm	Sport
Rear Nearside :	Falken	225/45 R18	5 mm	Sport
Rear Offside :	Falken	225/45 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 59 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$7,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 4 (Four) working days.

LCL APPRAISER PTE LTD

Vehicle Registration No.: SKB 7238 U

Our Ref No.:

FDK/01/2301/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front n/s headlamp	Damage	\$ 1,955.00	\$ 1,955.00	1045 X nm
1	Front bumper	Damage	\$ 1,887.00	\$ nn 1,887.00	X 2 x x x x x x
1	Front bumper clip (1 set)	Necessary	\$ 65.00	\$ nn 65.00	
1	Front bumper n/s side retainer	Necessary	\$ 75.50	\$ nn 75.50	
1	Front n/s door	Repair	\$ 1,470.00	\$ nn 1,470.00	Ry
1	Front n/s fender	Damage	\$ 1,085.00	\$ 1,085.00	891
1	Front n/s fender inner shield	Damage	\$ 185.00	\$ nn 185.00	
			\$ 6,722.50	\$ 5,252.50	X x x x x x x
			\$ 336.13	\$ 262.63	
			\$ 6,386.38	\$ 4,989.88	X x x x x x x
				2261.50	
				2148.42	

SPECIAL NETT ITEMS

1	Front bumper lower spoiler	Damage	\$ 750.00	\$ 750.00	X nm
1	Front n/s fender inner shield clip (1 set)	Necessary	\$ 55.00	\$ 55.00	30 X nn
1	Front n/s tyre (Depreciation)	Damage	\$ 500.00	\$ 250.00	X nm
1	Front n/s wheel rim	Damage	\$ 1,250.00	\$ 1,250.00	X nm
			\$ 2,555.00	\$ 2,305.00	

Total cost of parts

\$ 8,941.38 \$ 7,294.88

L APPRAISER PTE LTD

Vehicle Registration No.: SKB 7238 U

Our Ref No.: FDK/01/2301/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 8,941.38	\$ 7,294.88

LABOUR

1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00	\$ 50.00 30 x
2	To conduct wheel alignment.	\$ 150.00	\$ 150.00 xu
3	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 30 20
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 500 250
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00 250
6	To diagnose erase fault memory after repair.	\$ 300.00	\$ 300.00 200 x 1420

GRAND TOTAL

\$ 11,651.38	\$ 9,264.88
---------------------	--------------------

~~2148.42~~
~~30~~
~~1420~~
~~3598.42~~
~~1/s\$2900~~
~~3 days#~~
2 days



Vehicle Registration No.: SKB 7238 U

Our Ref No.: FDK/01/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,400.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be void.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H.
Automotive Appraiser