Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Anand Kumar Ram Kumar @Muhammad Ridwan

Date

: 16 January 2023

Ashsiddiq Bin Abdullah

Our ref

: FDK/01/2301/TP

C/o: FDK Automobile & Leasing Services Pte Ltd

39 Woodlands Close

#05-12 Mega @ Woodlands Singapore 737856

Accident Date

: 1 January 2023

Type of Survey : Third Party

Inspection Date

10 January 2023

Repairer Name

FDK Automobile & Leasing Services Pte Ltd

39 Woodlands Close

#05-12 Mega @ Woodlands Singapore 737856

PARTICULARS OF VEHICLE

Registration No : SKB 7238 U

Year / Capacity:

2010 / 1597 cc

Make / Model

: Mercedes Benz C180K

Colour

Black

: WDD2040452A426247

Chassis No

Mileage

154589

Engine No

: 27191031330760

CONDITION OF TYRES

		Make Size		Thread Balance	Rim	
Front Nearside	:	Falken	225/45 R18	5 mm	Sport	
Front Offside		Falken	225/45 R18	5 mm	Sport	
Rear Nearside	â	Falken	225/45 R18	5 mm	Sport	
Rear Offside	20	Falken	225/45 R18	5 mm	Sport	

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s front portion. (Details refer to the photographs attached)

Enclosed number of photographs:

59

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$7,400.00 on a contractual basis.

Under normal circumstances, the repair period would be about 4 (Four) working days.



Vehicle Registration No.: SKB 7238 U

Our Ref No.:

FDK/01/2301/TP

Qty	Description	Conditions		Repairer's Estimate		Revised Amount	
Qıy	Description	Conditions					
	SPARE PARTS - LIST ITEMS						
1	Front n/s headlamp	Damage	\$	1,955.00	\$	1,955.00	
1	Front bumper	Damage	\$	1,887.00	\$	1,887.00	
1	Front bumper clip (1 set)	Necessary	\$	65.00	\$	65.00	
1	Front bumper n/s side retainer	Necessary	\$	75.50	\$	75.50	
1	Front n/s door	Repair	\$	1,470.00			
1	Front n/s fender	Damage	\$	1,085.00	\$	1,085.00	
1	Front n/s fender inner shield	Damage	\$	185.00	\$	185.00	
			\$	6,722.50	\$	5,252.50	
		Less 5%	\$	336.13	\$	262.63	
Total Cost - List Items			\$	6,386.38	\$	4,989.88	
	SPECIAL NETT ITEMS						
1	Front bumper lower spoiler	Damage	\$	750.00	\$	750.00	
1	Front n/s fender inner shield clip (1 set)	Necessary	\$	55.00	\$	55.00	
1	Front n/s tyre (Depreciation)	Damage	\$	500.00	\$	250.00	
1	Front n/s wheel rim	Damage	\$	1,250.00	\$	1,250.00	
	Total Cost - Special Nett items	5-	\$	2,555.00	\$	2,305.00	

Total cost of parts

\$ 8,941.38	\$ 7,294.88



Vehicle Registration No.: SKB 7238 U

Our Ref No.:

FDK/01/2301/TP

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	8,941.38	\$	7,294.88	
	<u>LABOUR</u>					
1	To check wiring, lighting and resetting headlamps focusing.	\$	80.00	\$	50.00	
2	To conduct wheel alignment.	\$	150.00	\$	150.00	
3	To apply undercoating on repaired and replaced panel.	\$	100.00	\$	60.00	
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,080.00	\$	750.00	
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,000.00	\$	660.00	
6	To diagnose erase fault memory after repair.	\$	300.00	\$	300.00	
	GRAND TOTAL	\$	11,651.38	\$	9,264.88	



Vehicle Registration No.: SKB 7238 U

Our Ref No.:

FDK/01/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 7,400.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser



































































































