

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA23001442/KNY3Q2**Date:** 02/05/2023**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP314343
Claimant Vehicle No :	SND1817S	Insured Vehicle No :	SLX6965H
Date of Loss:	08/02/2023	Nature of Claim:	TP
		Claim No:	MPC03981/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND1817S		
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 (A)	Engine No:	G4LEMU133226
Reg. Date:	13/12/2021 (Man. Year: 2021)	Chassis No:	KMHC851CVMU262902
Colour:	Metalic Light Grey	Odometer:	81169 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 7 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Wanli 7 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,385.32	4,474.36	910.96	16.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	950.00	3,030.00	76.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,365.32	5,424.36	3,940.96	42.08
+ GST 8.00/8.00% (S\$)	749.23	433.95	315.28	42.08
Nett Amount (S\$)	10,114.55	5,858.31	4,256.24	42.08

INSPECTION

Date of Assignment:	09/02/2023		
Date Inspected:	10/02/2023	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 May 2023)	
Parts:	N/A	HYUNDAI AE IONIQ HEV 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND1817S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FRONT BUMPER	Buckled / Cracked	452.40 FL	*452.40 FL
2	1		*COVER -RADIATOR GRILLE UPPER	Serviceable	48.30 FL	*- FL
3	1		*ABSORBER -FRONT BUMPER ENERGY	Serviceable	86.90 FL	*- FL
4	1		*MOULDING -FRONT BUMPER CENTER ,UPPER	Dented	297.10 FL	*297.10 FL
5	1		*BRACKET -FRONT BUMPER SIDE ,LH	Distorted	28.00 FL	*28.00 FL
6	1		*LAMP ASSY -HEAD ,LH	Mtg Cracked	2,110.30 FL	*2,110.30 FL
7	1		*LAMP ASSY -DAY RUNNING LIGHT ,LH	Mtg Cracked	642.50 FL	*642.50 FL
8	1		*MOULDING -FRONT BUMPER ,LH	Dented / Cut	93.00 FL	*93.00 FL
9	1		*GRILLE ASSY -RADIATOR	Serviceable	460.20 FL	*- FL
10	1		*FENDER SUB-ASSY ,FRONT LH	Bent	588.80 FL	*588.80 FL
11	1		*LINER ,FRONT FENDER -LH	Cracked	114.70 FL	*114.70 FL
12	1		*HUB CAP	Dented	235.60 FL	*235.60 FL
13	1		*FENDER CLIP	Not Necessary	130.00 FS	*- FS
14	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
15	1		*RADIATOR GRILLE CLIP	Not Necessary	65.00 FS	*- FS
16	1		*FRT LH BUMPER SIDE CLIP	Not Necessary	65.00 FS	*- FS
17	1		*FRT RH BUMPER SIDE CLIP	Not Necessary	65.00 FS	*- FS
18	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
19	1		*TYRE	Serviceable	350.00 FS	*- FS
20	1		*CARRIER -FRONT END MODULE	Cracked	949.30 FL	*949.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,912.10	5,576.70
- List Item Discount on L Items 25.00/20.00% (\$\$)	1,526.78	1,102.34
Total Parts (\$\$)	5,385.32	4,474.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (S\$)			3,980.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >