

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

#### PARTICULARS OF CLAIM

|                               |                                 |                       |                   |
|-------------------------------|---------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (Own Damage)                 | Ref. No:              | OD/022023/5974    |
| Policy No:                    | SP2003011719-01                 | Date of Loss:         | 21/01/2023        |
| Vehicle Reg. No.:             | <b>SMF1714G</b>                 | Driveable?            |                   |
| Driver Age/Info:              | 38 / MALE                       | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                              | Third Party Involved? | NO                |
| Insured/Claimant:             | WANG BIAODONG                   | Contact No:           | +6598526601       |
| Driver:                       | WANG BIAODONG                   |                       |                   |
| Make/Model:                   | TOYOTA HARRIER, 2.0 M GRADE (A) | Vehicle Reg. Date:    | 30/10/2018        |
| Vehicle Colour:               | White                           |                       |                   |
| Engine No:                    | 8ARZ141711                      | Chassis No:           | JTEZB3GH80J003376 |
| Odometer:                     | 0 KM                            |                       |                   |
| Paint Type:                   |                                 |                       |                   |
| Total Loss?                   | <b>NO</b>                       |                       |                   |
| Est. Duration of Repair (day) | 8                               |                       |                   |
| Description of Accident/Loss  | REFER TO SKETCH                 |                       |                   |
| Present Location:             | VIN'S MOTOR PTE LTD (SIN MING)  |                       |                   |

#### COST OF CLAIMS

|                           | Amount           |
|---------------------------|------------------|
| Parts                     | 16,373.00        |
| Miscellaneous Items       | 0.00             |
| Labour                    | 1,690.00         |
| Paintwork Labour          | 980.00           |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>19,043.00</b> |
| <b>+ GST 8.00% (\$\$)</b> | <b>1,523.44</b>  |
| <b>Nett Amount (\$\$)</b> | <b>20,566.44</b> |

This claim is handled by: MUHAMMAD ISWAN BIN ISHAK



## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2023)

**Parts:** M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Vin's Motor Pte Ltd/SMF1714G/09/02/2023 15:46

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                        | %Disc | %Depr | Amount      |
|-----|-----|----------|------------------------------------|-------|-------|-------------|
| 1   | 1   |          | *BONNET CHROME MOULDING            | 0.00  | 0.00  | *250.00 F   |
| 2   | 1   |          | *RH HEADLAMP                       | 0.00  | 0.00  | *3,100.00 F |
| 3   | 1   |          | *LH HEADLAMP                       | 0.00  | 0.00  | *3,100.00 F |
| 4   | 1   |          | *RH HEADLAMP SPONGE (WHITE)        | 0.00  | 0.00  | *40.00 F    |
| 5   | 1   |          | *LH HEADLAMP SPONGE (WHITE)        | 0.00  | 0.00  | *40.00 F    |
| 6   | 1   |          | *RH HEADLAMP LOWER BRACKET         | 0.00  | 0.00  | *50.00 F    |
| 7   | 1   |          | *LH HEADLAMP LOWER BRACKET         | 0.00  | 0.00  | *50.00 F    |
| 8   | 1   |          | *FRONT GRILLE                      | 0.00  | 0.00  | *620.00 F   |
| 9   | 1   |          | *FRONT GRILLE RH BRACKET           | 0.00  | 0.00  | *60.00 F    |
| 10  | 1   |          | *FRONT GRILLE LH BRACKET           | 0.00  | 0.00  | *60.00 F    |
| 11  | 1   |          | *FRONT GRILLE EMBLEM               | 0.00  | 0.00  | *580.00 F   |
| 12  | 1   |          | *FRONT RADAR WITH BRACKET          | 0.00  | 0.00  | *950.00 F   |
| 13  | 1   |          | *FRONT BUMPER                      | 0.00  | 0.00  | *1,100.00 F |
| 14  | 1   |          | *FRONT BUMPER CENTER LOWER GRILLE  | 0.00  | 0.00  | *200.00 F   |
| 15  | 1   |          | *FRONT BUMPER CENTER LOWER GARNISH | 0.00  | 0.00  | *280.00 F   |
| 16  | 1   |          | *FRONT BUMPER RH FOG LAMP          | 0.00  | 0.00  | *170.00 F   |
| 17  | 1   |          | *FRONT BUMPER LH FOG LAMP          | 0.00  | 0.00  | *170.00 F   |
| 18  | 1   |          | *FRONT BUMPER RH FOG LAMP BRACKET  | 0.00  | 0.00  | *90.00 F    |
| 19  | 1   |          | *FRONT BUMPER LH FOG LAMP BRACKET  | 0.00  | 0.00  | *90.00 F    |
| 20  | 1   |          | *FRONT BUMPER LOWER PAD            | 0.00  | 0.00  | *250.00 F   |
| 21  | 1   |          | *FRONT BUMPER RH SIDE RETAINER     | 0.00  | 0.00  | *60.00 F    |
| 22  | 1   |          | *FRONT BUMPER LH SIDE RETAINER     | 0.00  | 0.00  | *60.00 F    |
| 23  | 1   |          | *FRONT BUMPER TOP BEAM             | 0.00  | 0.00  | *150.00 F   |
| 24  | 1   |          | *FRONT BUMPER SPONGE               | 0.00  | 0.00  | *60.00 F    |
| 25  | 1   |          | *FRONT BUMPER REINFORCEMENT        | 0.00  | 0.00  | *280.00 F   |
| 26  | 10  |          | *FRONT BUMPER CLIPS                | 0.00  | 0.00  | *20.00 F    |
| 27  | 1   |          | *FRONT SUPPORT PANEL               | 0.00  | 0.00  | *570.00 F   |
| 28  | 1   |          | *BRACE PANEL                       | 0.00  | 0.00  | *260.00 F   |
| 29  | 1   |          | *AIRCON CONDENSER                  | 0.00  | 0.00  | *1,100.00 F |
| 30  | 1   |          | *INTER COOLER                      | 0.00  | 0.00  | *420.00 F   |
| 31  | 1   |          | *RADIATOR TOP RH SIDE GUIDE        | 0.00  | 0.00  | *50.00 F    |
| 32  | 1   |          | *RADIATOR TOP LH SIDE GUIDE        | 0.00  | 0.00  | *50.00 F    |
| 33  | 1   |          | *RADIATOR LOWER RH SIDE GUIDE      | 0.00  | 0.00  | *50.00 F    |
| 34  | 1   |          | *RADIATOR LOWER LH SIDE GUIDE      | 0.00  | 0.00  | *50.00 F    |
| 35  | 1   |          | *FRONT NO. PLATE                   | 0     | 0.00  | *40.00 FS   |
| 36  | 1   |          | *FRONT BUMPER PARKING SENSOR       | 0     | 0.00  | *380.00 FS  |
| 37  | 1   |          | *COOLANT                           | 0     | 0.00  | *80.00 FS   |

F=Franchise part. S=SpcNett.

|                                          |                  |
|------------------------------------------|------------------|
| <b>Sub Total (\$)</b>                    | <b>14,930.00</b> |
| <b>+ Margin on L,N Items 10.00% (\$)</b> | <b>1,443.00</b>  |
| <b>Total Parts (\$)</b>                  | <b>16,373.00</b> |

Vin's Motor Pte Ltd/SMF1714G/09/02/2023 15:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No                             | Particulars              | Lab.Type | Amount          |
|--------------------------------|--------------------------|----------|-----------------|
| <b>Paintwork Labour</b>        |                          |          |                 |
| 1                              | TO SPRAY PAINTING        | New      | 980.00          |
| <b>Labour Items</b>            |                          |          |                 |
| 2                              | TO REFILL AIRCON GAS     | New      | 150.00          |
| 3                              | TO RESET HEADLAMP SYSTEM | New      | 280.00          |
| 4                              | TO RESET RADAR SYSTEM    | New      | 380.00          |
| 5                              | TO REPAIR DAMAGES        | New      | 880.00          |
| <b>Gross Labour Cost (S\$)</b> |                          |          | <b>2,670.00</b> |