



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8567Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LAMP ASSY-REAR FOG	NOT NECESSARY	201.50	-
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	294.80	-
2	REAR BUMPER REINFORCEMENT N/S & O/S LOWER BRACKET	NOT NECESSARY	20.00	-
1	REAR BUMPER REINFORCEMENT CENTRE LOWER BRACKET	NOT NECESSARY	15.00	-
2	REAR BUMPER N/S & O/S STAY	NOT NECESSARY	276.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET	NOT NECESSARY	66.20	-
1	REAR BUMPER LOWER MOULDING CENTRE	CRACKED	216.50	216.50
1	REAR BUMPER LOWER COVER	TO REPAIR SEE LABOUR	47.50	-
1	REAR BUMPER CAP HOOK	NOT NECESSARY	9.10	-
2	REAR BUMPER N/S & O/S REFLECTOR @\$31.90	NOT NECESSARY	63.80	-
	LESS 20% DISCOUNT		-334.00	-135.18
			1,336.00	540.72
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR NUMBER PLATE WITH CASING (SN)	CRACKED	50.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			428.00	50.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00

Report Ref No. CS/SMR23001446/Sqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, REAR BUMPER, REAR BUMPER CENTRE MOULDING, ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER COVER.		850.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL, REAR BUMPER LOWER CENTRE MOULDING (SILVER), REAR BUMPER LOWER COVER (SILVER).		800.00	500.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
			2,080.00	810.00
GRAND TOTAL			3,844.00	1,400.72
RECOMMENDED COST OF REPAIRS				1,400.00

Report Ref No. CS/SMR23001446/Sqy3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.