

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

13-Feb-23

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHE 8567 Z

1 pc	Lamp Assy- Rear fog X NN	\$ 459.40
1 pc	Rear bumper Cra	\$ 294.80
1 pc	Rear bumper reinforcement X NN	\$ 20.00
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket X NN	\$ 45.00
1 pc	Rear bumper reinforcement centre lower bracket X NN	\$ 276.20
2 pcs	Rear bumper n/s & o/s stay X NN	\$ 66.20
2 pcs	Rear bumper n/s & o/s side bracket X NN	\$ 216.50
1 pc	Rear bumper lower moulding centre Cra	\$ 47.50
1 pc	Rear bumper lower cover Sur R	\$ 9.10
1 pc	Rear bumper cap hook X NN	\$ 63.80
2 pcs	Rear bumper n/s & o/s reflector @ \$31.90 X NN	\$ 1,670.00
Less 20%		\$ 334.00
		\$ 1,336.00

S/Nett

1 set	Rear bumper clips X NN	\$ 48.00
1 set	Reverse sensor X NN	\$ 280.00
1 pc	Rear number plate with casing Cra	\$ 50.00
Sundry		\$ 50.00 X NN
To check wiring		\$ 50.00 30
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, rear bumper, rear bumper centre moulding, etc		\$ 850.00 200
To putty and spray painting on rear bumper, end panel, rear bumper lower centre moulding (Silver), rear bumper lower cover (Silver)		\$ 800.00 500
To apply rustproofing on the repaired and replaced panels.		\$ 80.00 X NN
		\$ 3,844.00 860

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

2 days 6/8 P/P
13/2/23 330pm
1rfm
P/P = 1400