

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23001448/UPA3Q2**Date:** 11/05/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000689490-01
Claimant Vehicle No : SJE234Y **Insured Vehicle No :** SMG1608A
 Date of Loss: 06/02/2023 Nature of Claim: TP Claim No: 202332005259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE234Y**
 Make & Model: LAND ROVER RANGE ROVER EVOQUE, 2.0 TSS (A) Engine No: 015124140954204PT
 Reg. Date: 16/11/2017 (Man. Year: 2017) Chassis No: SALVA2AG6HH226530
 Colour: Grey Odometer: 64268 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,406.65	6,143.19	6,263.46	50.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	650.00	600.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,656.65	6,793.19	6,863.46	50.26
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	13,656.65	5,400.00	8,256.65	60.46
+ GST 8.00/8.00% (S\$)	1,092.53	432.00	660.53	60.46
Nett Amount (S\$)	14,749.18	5,832.00	8,917.18	60.46
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		57.75		
Nett Liability (S\$)		6,289.75		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 10/02/2023
 Date Inspected: 10/02/2023 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2023)
Parts:	M1-SUV	LAND ROVER RANGE ROVER EVOQUE 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE234Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed / Torn	3,327.22 FN	*3,327.22 FN
2	1		*FRONT BUMPER LOWER GUARD -CTR	Torn	1,560.93 FN	*850.00 FN
3	2		*FRONT BUMPER PDC SENSOR	Not Necessary	562.66 FN	*- FN
4	2		*FRONT BUMPER SPRAY NOZZLE COVER -R/L	Not Necessary	179.90 FN	*- FN
5	1		*FRONT BUMPER TOP GUIDE -CTR	Cracked	441.59 FN	*441.59 FN
6	2		*FRONT BUMPER SIDE GUIDE -R/L	Not Necessary	220.50 FN	*- FN
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,855.90 FN	*- FN
8	1		*FRONT GRILLE ASSY	Cracked	1,655.23 FN	*1,005.22 FN
9	1		*AIR INTERCOOLER	Not Necessary	1,860.59 FN	*- FN
10	1		*AIR INTERCOOLER INTAKE DUCT	Torn	221.43 FN	*221.43 FN
11	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
12	1		*SET FRONT NUMBER PLATE WITH HOLDER	Bent	65.00 FS	*40.00 FS
13	1		*SET FRONT BUMPER WRAP STICKER	Necessary	1,000.00 FS	*500.00 FS
					Sub Total (\$\$)	13,000.95 6,435.46
					- Nett Item Discount on N Items 5.00/5.00% (\$\$)	594.30 292.27
					Total Parts (\$\$)	12,406.65 6,143.19

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	0.00
2	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	600.00	350.00
3	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS	New	600.00	300.00
Gross Labour Cost (S\$)			1,250.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >